

Veridian Petrochemicals
Bharuch Complex

Document no: TEST-PSV-4101-2026 Revision: A
Title: Bench test and reset, PSV-4101
Owner: Gopal Iyer
Issued: 03 April 2026

Primary equipment: PSV-4101, Flare header relief valve

Tester: Gopal Iyer
Equipment: PSV-4101

Popped within tolerance of the set pressure on the third lift.
Seat tight after reset.
Seal wire and tag renewed.
Result: passed.