

Veridian Petrochemicals
Bharuch Complex

Document no: TEST-V-4101-2026 Revision: A
Title: External inspection and thickness survey, V-4101
Owner: Gopal Iyer
Issued: 31 March 2026

Primary equipment: V-4101, Flare knock-out drum

Tester: Gopal Iyer
Equipment: V-4101

Minimum measured wall 13.5 mm at the survey points.
No active leaks, coating in sound condition.
Supports, nozzles and platforms examined.
Result: passed with an observation.