

Veridian Petrochemicals
Bharuch Complex

Document no: TEST-V-4102-2026 Revision: A
Title: External inspection and thickness survey, V-4102
Owner: Gopal Iyer
Issued: 12 July 2026

Primary equipment: V-4102, Flare seal drum

Tester: Gopal Iyer
Equipment: V-4102

Minimum measured wall 19.9 mm at the survey points.
No active leaks, coating in sound condition.
Supports, nozzles and platforms examined.
Result: passed.