

Customer : ZHEJIANG GIEN (KCD)

Date : 28 MAY 2019

Time : 10am ~ 1.00pm

	Name	Position
Team Leader:	Mr Zamri	Asst Manager
Internal team members:	Mr Mori	Sales Manager
	Mr Eric	Sales Manager
External team members:	Mr Jason	General Manager
	Mr Davis Zhang	Purhasing Engineer
	Mr Jerry	Quality Manager

Agenda

: Quality Isssue For Product 4.5x4.5x0.38t (Laser) at KCD

□ Details Discussion : Quality Issue

s/n	Item	Corrective Action/ Comment (KCD)	MM Comment	Responsible	Target Date	Status
1	Warp	1.Drawing Show warp spec 0.23 and using glass gauge 0.61mm.But KCD using glass gauge 0.60.KCD checking glass gauge using filler gauge. 2.Need consider glass material and the flatness of the glass because kcd using special glass.Thickness glass 10mm thick. 3.KCD finding our glass gauge small not cover all the surface ceramic 4.KCD already sort less than 20k warp.	1. MM Using glass gauge 0.61mm but confirm check using pin gauge&Master Product. 2.MM will check for this item and find the good supplier glass with can give flatness zero. 3.MM will reset change glass to big size and will send one set glass gauge to Zhejiang for verified.	Mr Zamri	14 June 2019	Open
2	Pelling	1.KCD need to understand how MM can stop this peeling issue.Feedback from KCD in our surface ceramic have two type of mode.	1.Take the NG sample bring to Malaysia for future analysis	Mr Zamri	14 June 2019	Open
3	Crack (Chipping)	KCD facing chipping issue after their process laser.Customer worry this chipping can cause crack issue.	Chipping Check before Laser process at customer within spec 3mmx1mm(XY).Request Ng sample for MM doing future analysis	Mr Zamri	14 June 2019	Open