

Substrate Sorting Result
Abnormal Crack
Maker MARUWA

Date 15~20 Aug'2014

Type	No.	AQL no.	Lot no.	Q'ty (Sheet)	Sorting Result		
					NG	OK	
YR762BR	1	14B-07-001	GK36-1	106,080	1,351	104,729	Finished
	2	14B-07-006	GK40-KK	50,340	752	49,588	Finished
	3	14B-07-009	LD91-KK	136,320	1,481	134,839	Finished
	4	14B-07-010	LD93-KK	38,880	437	38,443	Finished
	5	14B-08-001	FG27-1	61,440	744	60,696	Finished
R1532LRW	6	14B-07-013	AV01	300	0	300	Finished
	7	14B-07-013	AV98	6,500	92	6,408	Finished
	8	14B-06-007	AV42	21,700	297	21,403	Finished
	9	14B-06-007	AV73	21,200	331	20,869	Finished
AR308HRW	10	14B-07-012	PH07-KK	90,720	970	89,750	Finished
Total				533,480	6,455	527,025	533,480

1.21% 98.79%