

Customer: **PANASONIC JAPAN** Date: **15-Feb-19** Time: **9:00**

Participant From Maruwa		Participant From Organizer	Report To
1. Mr Tsuda	MM SUB	1.	1. Mr.Anthony,Mr.Ogawa
2.		2.	2. Mr.Seeni,Mr.Naga,Mr.Sinna
3.		3.	3. Mr,SIVA Mr,INAGAKI
4		4	4 Mr.Theva,Mr.Fauzi
5.		5.	5. Mr Loga, Mr Matsumoto

Agenda

Start inspection 9:00am at the Panasonic factory

Result of sorting 15th feb 2019

ALT8GKB 板厚選別結果										
検査日	品番	前半ロット№	抵抗体Lot. NO	ランク	電圧Lot	検査前数量	ゲージ数量	検査重量	不良数量	備考
2月15日	7RQF6R81 B	439208098	92G7-0618	43	2F91LA21	58,782	4,703	38	0	
	7RNF2741 P	439201163	9242-0108	43	2F91PC02	662,140	52,971	424	0	
	U07F80R6A	439208054	9245-0608	44	2F8DJA15	56,204	4,496	36	0	
	7RQF2R0B	439208134	92G7-0617	43	2F91LA21	297,820	23,826	191	0	138,737
	7RNF2741 P	439201170	9242-0109	43	2F91PC02,01	659,264	52,741	422	0	1,734,210

Summary of the result 15-Feb-19 Sampling plan & method

Total Lot inspected : 5 lots

today Total qty 1,734,210 pcs

over all total 49,114,995pcs/139lot

NG 0pcs

a. Quantity, Panasonic data

b. Product inspection is done with a jig

Conclusion & Opinion

inspection 5lot

have waiting lot today but i can inspection NG lot

still have another NG lot 2lot abut 500,000pcs

dont have another lot

im come back malaysia tomorow