

11

Prototype

Pre-Launch

Production

Date (Original)

18/01/18

Part Name:- Shaft Pinion Z-12
Helical LH

Part No.:- D10687470A

Inspection Standard Number	SIP/4242/160
----------------------------	--------------

Customer :- Escorts

Change Level.: -00

Part Stage

HT Lab.

[illegible]

CONTROLLED COPY

LSR NC

ISSUED TO Unit-7

DATE 20/6/2024

OPET. SKTCH

Material:-20Mn5Cr5-S



Core Hardness


Figure 1- 1 Measured at this Location

ECD On Ground Diameter.
0.8mm Min. Up To 513 HV

Surface Hardness On
Ground Diameter.
54HRC Min.

Surface Hardness On
Ground Diameter.
/ 54HRC Min.

Effective Case Depth



Core Hardness
Measured at
this Location

Figure 1-2

Reaction Plan: A-यदि Inspection करते समय कम्पोनेंट खराब मिले तो खराब कम्पोनेंट को Rejection का टैग लगाकर Rejection टेबल पर रखें और उसके बारे में Department के Incharge को बतायें।

Legends:

► Special Characteristics as Per Drawing

* Special Characteristics For Process

 Special Characteristics For Safety

Change Details

Change Details							
Date	Rev. No.	Change	Reason for Change	Date	Rev. No.	Change	Reason for Change

Checked By:

Approved By: