

NBC Chandler, AZ

4040 S ARIZONA AVENUE SUITE H-13 Chandler, AZ 85248

BRETON | AVENIR
CONSTRUCTION SERVICES

Date Fri 05/08/2026

Job # B26.004

Prepared By Joshua Vardakas



Weather

6:00 AM

70° 

Clear

Wind: 6 MPH | Precipitation: .0" | Humidity: 29%

12:00 PM

89° 

Clear

Wind: 5 MPH | Precipitation: .0" | Humidity: 14%

4:00 PM

99° 

Clear

Wind: 14 MPH | Precipitation: .0" | Humidity: 10%

Work Logs

Name	Description	Quantity	Total Hours
 BC plumbing	— Joshua Vardakas 5/8/26, 6:56 PM	1	6
 Westgate Elec	— Joshua Vardakas 5/8/26, 6:57 PM	2	4
 graphic installer	— Joshua Vardakas 5/8/26, 6:57 PM	1	2
 southwest gas	— Joshua Vardakas 5/8/26, 6:58 PM	1	3
Total		5	15

Work Log Photos


BC plumbing: | QTY: 1 | HRS: 6.0 ↩



Westgate Elec: | QTY: 2 | HRS: 2.0 ↩



graphic installer: | QTY: 1 | HRS: 2.0 ↩




southwest gas: | QTY: 1 | HRS: 3.0 ↩




Equipment	No entry
General Notes	No entry
Site Safety Observations	No entry
Quality Control Observations	No entry

Survey				
Questions	N/A	No	Yes	Description
1. Did any inspections happen today? if so which? (Take picture of sign off)	☐	☒	☐	
2. Any schedule delays occur? Please explain.	☐	☒	☐	
3. Any weather delays occur?	☐	☒	☐	
4. Any visitors on site?	☐	☒	☐	
5. Was there any deliveries today? 	☐	☐	☒	
6. Any equipment rented on site? 	☐	☐	☒	portopotty, dumpster, mobile mini, pallet jack
Joshua Vardakas 05/08/26 06:59PM				
7. Was there any changes/discrepancy in the plans or subcontractor Change orders?	☐	☒	☐	






Survey Photos	
5.	



6. ↩



Attachments





I, Joshua Vardakas, have reviewed and completed this report.

Joshua Vardakas | 05/08/26 | 07:00PM