






Daily Field Report - SaskPower








Information

 4B-298 KENOSEE NE (20319338)

 X-Terra Environmental

 Friday, February 14th 2025, 3:25 PM (CST -06:00)

Project Details

Proponent:	 SaskPower
Location:	 NW-12-11-02 W2M
Project Name:	 4B-298 KENOSEE NE (20319338)
Vendor and Foreman:	 None
X-Terra Project Number:	 25600
Environmental Monitor:	 Jeff Kardas
ENV File Number:	 N/A

Project Activities

Project Activities:

 06:15 – Leave Moosomin for project site 20319338.

07:00 – Arrive at project site. Complete site specific tailgate.

Conducted nest sweeps/species surveys within areas of the project located within grassland/nesting habitat identified during the secondary screening. One active American Robin nest was noted in a stand-alone aspen tree in SE-4-11-2 W2M (GPS Coordinates: 49.873837, -102.210973). The adult robin was seen perched in the nest. The nest was too high to observe the contents, though no chicks were heard or seen in the nest. As such, it is assumed the young are in the egg stage. The nest was marked with survey stakes and flagging tape.





A nest with a singular egg was located near recently cleared brush at the boundary between NE/NW-12-11-2 W2M. The brush surrounding the nest had already been flagged off, as it appeared crews stopped working when they saw the nest. This was likely flagged off previously during a crew nest sweep. No adult was noted in the area; the egg/nest may be abandoned.

13:45 – Finish nest sweep/species survey of the project area. Head back to Saskatoon.

18:45 – Arrive in Saskatoon.

Total Hours Worked:	 12.5
---------------------	--

 No NA Completed/Reviewed X-Terra Tailgate:

Yes	No	<div>NA</div>	Reviewed/Signed Crew Tailgate:
Yes	No	<div>NA</div>	Reviewed Permit(s) with Crew(s)
X-Terra Equipment Onsite: <div><div>✓</div> None</div>			
Weather and Ground Conditions: <div><div>≡</div> Wind 22 km/h, temperatures 29°C. Dry ground conditions.</div>			
Environmental Protection Measures and Mitigation: <div><div>≡</div> Stay on existing trails and roads as much as possible, work within project boundary. Follow sensitive species setbacks and timing windows. Avoid work near active nest until young are fledged.</div>			
Wildlife Observations: <div><div>≡</div> American Crow, Eastern Kingbird, Cedar Waxwing, Red-tailed Hawk, Brown Thrasher, American Robin, Vesper Sparrow, Clay Coloured Sparrow</div>			
Future Monitoring Requirements (how many monitoring days left, are crews returning from break, etc.): <div><div>≡</div> If project activities are not started within 7 days a re-sweep will be required.</div>			
Additional Photos			
<div><div><div>Viewing active robin nest.</div></div><div><div>Viewing south to flagging around robin nest.</div></div><div><div>Viewing nest area flagged by crews.</div></div><div><div>Viewing southeast to area flagged by crews.</div></div></div>			

Signatures

Jeff Kardas , *Manager, Reclamation & Remediation*



February 14th 2025, 3:25 PM (CST -06:00)



52.1911312, -106.6328176

A handwritten signature in black ink, appearing to be 'JK' or similar, located to the right of the name and title.