













Daily Field Report - SaskPower

Information

-  4D74 Veg Management (20281748)
-  X-Terra Environmental
-  Friday, February 14th 2025, 3:19 PM (CST -06:00)

Project Details

Proponent:	 SaskPower
Location:	 Various
Project Name:	 4D74 Veg Management (20281748)
Vendor and Foreman:	 Kitsaki (Glen Zelensky)
X-Terra Project Number:	 25600
Environmental Monitor:	 Jeff Kardas
ENV File Number:	 21-16-00036

Project Activities

Project Activities:

 06:30- Left Hudson Bay for project area.

07:30 - Arrive at project area, meet Kitsaki crew. One of the slashing crew members is sick and will not be onsite today. Completed X-Terra hazard assessment and signed onto Kitsaki hazard assessment. Reviewed ENV permit with Kitsaki crew.

Towards the end of the day yesterday one of the mulchers was having mechanical issues. The Kitsaki foreman completed a field repair this morning and the mulcher appears to be in working order.







08:30 - Kitsaki crews continued working. Slash crew member continuing to hand clear wetland vegetation at Site #3 while mulchers work to continue mechanical clearing at Site #6.

11:30 - The same mulcher that had a mechanical issue in the morning had the same issue re-occur. The Kitsaki foreman send the semi driver to get a new mulcher and bring it to the project. In the meantime, crews will continue slashing Site #6 with one mulcher.

13:30 - The second hand slash crew member was feeling better and arrived onsite. Hand slash crew continued slashing wetland vegetation at Site #3.

Continued nest sweeps in wetland area at Site #4 that is scheduled for hand clearing.

Total Hours Worked:  7

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> NA	Completed/Reviewed X-Terra Tailgate:
<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> NA	Reviewed/Signed Crew Tailgate:
<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> NA	Reviewed Permit(s) with Crew(s)
X-Terra Equipment Onsite: <input checked="" type="radio"/> None			
Weather and Ground Conditions: ☰ Sunny, wind 6-12 km/hr, temperatures 14-25°C. Dry ground conditions.			
Environmental Protection Measures and Mitigation: ☰ All permit conditions in Ministry of Environment Permit #21-16-00036 were followed.			
Wildlife Observations: ☰ Broad-winged Hawk, Common Raven, American Crow, Brewer's Blackbird, Red-eyed vireo			
Future Monitoring Requirements (how many monitoring days left, are crews returning from break, etc.): ☰ Monitoring will continue tomorrow (August 7).			
Additional Photos			
<div>  <p>Viewing north to Site #8.</p> </div> <div>  <p>Viewing north to crews mulching Site #7.</p> </div> <div>  <p>Viewing north to south end of Site #6.</p> </div> <div>  <p>Viewing south to north end of Site #6.</p> </div> <div>  <p>Viewing southeast to wetland area swept at Site #4.</p> </div> <div>  <p>Viewing north to Site #7 at end of day.</p> </div>			

Signatures

Jeff Kardas , *Manager, Reclamation & Remediation*



February 14th 2025, 3:19 PM (CST -06:00)



52.1911591, -106.6328494

A handwritten signature in black ink, appearing to be 'Jeff Kardas'.