MyWalkThru Report

Tenant: John Smith

Lease Begins: 3/12/2017

Report Date: 4/7/2017



PROPERTY LOCATION	PROPERTY MANAGER
5915 Oak Blossom	Home Run Property Management, LLC.
San Antonio, TX 78250	Jane Doe
	(555) 555-5555
	janedoe@homerunproperties.com

This report is an assessment of the condition of the property on the date shown and only the items listed in the report with notations made are reported on. This report is for the use of the property manager and/or owner to see first hand the condition of the property address as shown on the report. If no safety issues or deficiencies are observed, NO COMMENTS will be made.

SUMMARY OF ITEMS THAT NEED ATTENTION

Front Exterior

Roof/Trim

Bent Gutter 02/16/2017 7:30 PM (CST)



Front Exterior

Walls/Siding/Trim

Caulked joints of siding are beginning to crack 02/16/2017 7:30 PM (CST)


END OF SUMMARY

PROPERTY DET		Net Applicable	Noode Attention
Front Exterior 1. Driveway	Observed	Not Applicable	Needs Attention
2. Garage Door			
3. Yard			
4. Mail Box			×
1.1.	5/26/2015 1:00 PM		
Driveway			
1.2.	5/26/2015 2:00 PM		

5/26/2015 3:00 PM

Driveway

2.1.




Garage

3.1. 5/26/2015 5:00 PM



Yard

3.2. 5/26/2015 6:00 PM



Address Box

4.2. 5/26/2015 8:00 PM



Flag

Close Out Details and Signature	
Tenant Signature	
Hamp-	

NOTES

Lorem ipsum dolor sit amet, audiam persius disputationi at usu, cum posse ocurreret at, commodo viderer id est. Te solet gloriatur pri, detraxit hendrerit usu in. Agam ferri nostrum et sed. Ad sea omnium voluptua honestatis. Tantas eripuit democritum has at, his in dicam concludaturque. Zril graeco ea sit, tation quidam saperet pro ei.

END OF REPORT