PETROLEUM FACILITY INSPECTION REPORT

Synthetic Test Document — All data is fictional and intended solely for prototype testing.

Inspection ID	MP-INS-2026-0471	**Inspection Date**	18 September 2026
Facility	Western Fuel Storage Depot – Unit 3	**Location**	Pune, Maharashtra
Inspector	R. Sharma	**Facility Type**	Petroleum Product Storage & Distribution Depot

Inspection Parameters

Parameter	Observation
Storage Tank ID	TK-03
Product	Diesel
Tank Capacity	50,000 KL
Current Level	37,420 KL
Tank Shell Condition	Minor surface corrosion observed
Inlet Pressure	4.8 bar
Outlet Pressure	4.5 bar
Temperature	31.6°C
Safety Valve	Functional
Emergency Shutoff	Functional
Fire Extinguishers	8 installed, 1 expired
Fire Hydrant	Operational
Pipeline Condition	Minor corrosion near joint J-17
Leakage Detected	No visible leakage
Earthing System	Resistance measured at 6.8 Ω
Required Earthing Limit	≤ 5 Ω
Warning Signage	2 damaged signs
PPE Compliance	91%
Housekeeping	Satisfactory
Previous Inspection	12 June 2026
Previous Finding	Pipeline corrosion
Corrective Action Status	Pending

Inspector Findings

1. Critical: Tank TK-03 earthing resistance measured **6.8** Ω, exceeding the specified 5 Ω limit.

2. High: One fire extinguisher has exceeded its service/inspection validity.

3. Medium: Corrosion observed around pipeline joint J-17.

4. Low: Two safety warning signs are damaged and require replacement.

5. No visible fuel leakage was detected during the inspection.

Recommended Corrective Actions

1. Inspect and repair the TK-03 earthing system immediately.

2. Replace/service the expired fire extinguisher.

3. Conduct thickness/corrosion assessment around pipeline joint J-17.

4. Replace damaged safety signage.

5. Schedule a follow-up inspection after corrective actions are completed.

Overall Assessment

Overall Risk Status	**HIGH**
Compliance Status	**PARTIALLY COMPLIANT**
Follow-up Required	**YES**

Prototype testing notice: This document is synthetic. It does not represent an actual inspection, facility, inspector, ministry record, or government-issued document.