

Government Grievance Assessment Report

Case Identification

Grievance ID: G-20230216-001

Date of submission: on or around 14 February 2026

Nature of grievance: Complaint

Category: Environmental Issues

Subcategory: Water Pollution

Reported priority: High

Detailed Assessment and Case Study

The grievance submitted by a resident of Ambernath, Maharashtra, reports a severe case of water pollution and bad smell due to garbage dumped in a nala near their area. The image analysis confirms the presence of a large amount of garbage in the nala, causing significant contamination and water pollution. The location of the grievance is verified through the GPS overlay, which matches the user's report. The grievance has been classified as a complaint due to the explicit mention of a problem caused by a specific issue. The tone of the query is critical and concerned, typical of a complaint. The primary emotion expressed is anger, with secondary emotions of frustration and sadness. The severity level is critical, with a criticality score of 9, indicating a high risk of waterborne diseases, environmental pollution, and negative impact on local wildlife. The situation may escalate if not addressed promptly, leading to more severe consequences. The recommended department for addressing this issue is the Public Works Department (PWD) or Municipal Corporation of Ambernath. The grievance requires immediate attention to prevent further contamination and potential health risks. The expected resolution time is within 24-48 hours. The risk assessment is high, with a risk of waterborne diseases, environmental pollution, and negative impact on local wildlife. The situation may escalate if not addressed promptly, leading to more severe consequences. The similar cases data shows a recurring pattern of garbage dumping in water bodies in urban areas, particularly in India, where lack of proper waste management leads to pollution in water bodies. The image is likely to be genuine, but the similarity in patterns suggests that it may be part of a larger campaign to raise awareness about environmental issues. The use of a GPS Map Camera and the presence of a digital overlay suggest that the image is authentic, but the similarity in patterns and the lack of specific details about the incident make it difficult to determine the likelihood of spam. The policy search reveals government initiatives for water pollution control near Ambernath, complaint procedures, government responses, environmental protection laws, and grievance redressal mechanisms. The similar cases data shows a pattern of garbage dumping in public areas, lack of proper waste management infrastructure, and community involvement in maintaining cleanliness. The recommended department for addressing this issue is the Public Works Department (PWD) or Municipal Corporation of Ambernath. The grievance requires immediate attention to prevent further contamination and potential health risks. The expected resolution time is within 24-48 hours. The risk assessment is high, with a risk of waterborne diseases, environmental pollution, and negative impact on local wildlife. The situation may escalate if not

addressed promptly, leading to more severe consequences.