

**TRAFFIC COLLISION REPORT**

CHP 555 Format - Local Agency Adaptation Rev. 03-22 OPI 060

|                                            |                                              |                     |                                   |
|--------------------------------------------|----------------------------------------------|---------------------|-----------------------------------|
| <b>AGENCY:</b> Rivergate Police Department | <b>ORI:</b> CA0197400                        | <b>NCIC #:</b> 1974 | <b>OFFICER I.D.:</b> RPD #2814    |
| <b>LOCAL REPORT NO.:</b> TC-2025-1018      | <b>REPORTING DISTRICT:</b> RPD-04 (Downtown) | <b>BEAT:</b> 12     | <b>JUD. DIST.:</b> LASC — Central |

**SECTION I — CASE IDENTIFICATION**

|                                        |                                                                                                 |
|----------------------------------------|-------------------------------------------------------------------------------------------------|
| <b>Local Report Number</b>             | TC-2025-1018                                                                                    |
| <b>Number Injured</b>                  | 3                                                                                               |
| <b>Number Killed</b>                   | 0                                                                                               |
| <b>Collision Occurred On</b>           | S. Main Street                                                                                  |
| <b>At Intersection With / Milepost</b> | Third Avenue (bus stop on S. Main St. approx. 40 ft north of the north curb line of Third Ave.) |
| <b>City / County</b>                   | Rivergate / Los Angeles                                                                         |
| <b>Judicial District</b>               | Los Angeles Superior — Central                                                                  |
| <b>Reporting District</b>              | RPD-04 (Downtown)                                                                               |
| <b>Beat</b>                            | 12                                                                                              |
| <b>Date of Collision (MM/DD/YYYY)</b>  | 10/18/2025                                                                                      |
| <b>Day of Week</b>                     | Saturday                                                                                        |
| <b>Time (24hr)</b>                     | 0205 (02:05 a.m.)                                                                               |
| <b>NCIC #</b>                          | 1974                                                                                            |
| <b>Officer I.D.</b>                    | RPD #2814                                                                                       |
| <b>State Highway Related</b>           | No                                                                                              |
| <b>Photographs By</b>                  | Ofc. R. Delacruz #2814; Field Evidence Tech M. Cardenas                                         |
| <b>Tow Away</b>                        | Yes — bus removed by ACTD garage unit (non-commercial tow not required)                         |

**SECTION II — PARTIES****PARTY 1 — DRIVER**

|                                    |                                                                                                             |
|------------------------------------|-------------------------------------------------------------------------------------------------------------|
| <b>Party Number / Type</b>         | 1 — Driver                                                                                                  |
| <b>Name (First, Middle, Last)</b>  | Raymond T. Keeler                                                                                           |
| <b>Street Address</b>              | 1837 Alameda Street, Apt 4C                                                                                 |
| <b>City / State / ZIP</b>          | Rivergate, CA 91766                                                                                         |
| <b>Date of Birth</b>               | 04/11/1979                                                                                                  |
| <b>Sex</b>                         | M                                                                                                           |
| <b>Driver License No.</b>          | (California) Class B CDL — Passenger Endorsement (P)                                                        |
| <b>DL State / Class</b>            | CA / B                                                                                                      |
| <b>Endorsements / Restrictions</b> | P (passenger); DOT medical certificate on file                                                              |
| <b>Race</b>                        | H                                                                                                           |
| <b>Home Phone</b>                  | (626) 555-0100 (employer contact — ACTD Dispatch, night desk)                                               |
| <b>Business Phone</b>              | Same                                                                                                        |
| <b>Occupation</b>                  | Bus Operator, Alder Creek Transit District                                                                  |
| <b>Insurance Carrier</b>           | Self-insured public entity — Alder Creek Transit District (SIR); excess pool coverage on file with employer |
| <b>Policy Number</b>               | N/A (public entity SIR)                                                                                     |

**TRAFFIC COLLISION REPORT**

CHP 555 Format - Local Agency Adaptation Rev. 03-22 OPI 060

**Vehicle Identification — Party 1**

|                             |                                                                                                                                         |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|
| Vehicle Year / Make / Model | 2019 New Flyer XDE40 (transit bus)                                                                                                      |
| Body Type                   | Low-floor transit coach, 40 ft                                                                                                          |
| License Plate / State       | E-Plate exempt (public agency)                                                                                                          |
| VIN                         | On file with ACTD fleet records                                                                                                         |
| Fleet / Bus Number          | ACTD Bus #4177                                                                                                                          |
| Owner Name                  | Alder Creek Transit District                                                                                                            |
| Owner Address               | 1200 Alder Creek Way, Rivergate, CA 91766                                                                                               |
| Assignment                  | Owl Service — Block 512-OWL (Route 512)                                                                                                 |
| Direction of Travel         | Northbound                                                                                                                              |
| On Street / Highway         | S. Main Street                                                                                                                          |
| Speed Limit (Posted)        | 35 mph                                                                                                                                  |
| Vehicle Damage              | Major — front bumper, front destination sign panel, right front A-pillar, right forward passenger door frame; right-side mirror sheared |
| Damage Extent               | Major                                                                                                                                   |
| Refer to Narrative          | Yes                                                                                                                                     |

**PARTY 2 — PEDESTRIAN**

|                              |                                                                                                                            |
|------------------------------|----------------------------------------------------------------------------------------------------------------------------|
| Party Number / Type          | 2 — Pedestrian                                                                                                             |
| Name (First, Middle, Last)   | Yolanda Reyes                                                                                                              |
| Street Address               | 612 Poplar Street                                                                                                          |
| City / State / ZIP           | Rivergate, CA 91766                                                                                                        |
| Date of Birth                | 06/22/1991                                                                                                                 |
| Sex                          | F                                                                                                                          |
| Driver License No.           | Not required for pedestrian; identification confirmed via wallet ID on person                                              |
| Race                         | H                                                                                                                          |
| Occupation                   | Retail sales associate                                                                                                     |
| Injury Extent                | <b>Severe injury (Level 2) — airlifted from scene by air ambulance to Rivergate Regional Trauma Center.</b>                |
| Position at Time             | Standing at posted ACTD bus stop, east side of S. Main Street, north of Third Avenue (bus                                  |
| Movement Preceding Collision | Standing — waiting for southbound Owl service on opposite curb (per witness statement of P1 passenger Blau; see narrative) |

**SECTION III — OCCUPANTS OF PARTY 1 VEHICLE**

| Occ.  | Name           | Age | Seat / Location                             | Safety Equip.                   | Injury                                                                             | Disposition                                                          |
|-------|----------------|-----|---------------------------------------------|---------------------------------|------------------------------------------------------------------------------------|----------------------------------------------------------------------|
| Occ-1 | Devin Cho      | 23  | Fwd pass. cabin, right-side transverse seat | Lap belt not required (transit) | Complaint of pain — right lower leg deformity; brief LOC reported by co-pass. Blau | Transported Code 3 by RFD Medic 11 to Rivergate Regional Trauma Ctr. |
| Occ-2 | Alicia Mowbray | 40  | Mid-cabin, port-side longitudinal seat      | N/A                             | Complaint of pain — neck, low back, bilat. knees; multiple contusions              | Transported Code 2 by RFD Medic 14 to Rivergate Regional Trauma Ctr. |
| Occ-3 | Terrence Blau  | 30  | Aft cabin, port-side                        | N/A                             | None reported                                                                      | Not transported; on-scene statement to reporting officer             |

**SECTION IV — PROPERTY DAMAGED (OTHER THAN VEHICLES)**

**TRAFFIC COLLISION REPORT**

CHP 555 Format - Local Agency Adaptation Rev. 03-22 OPI 060

|                         |                                                                                                                                                                                                                                       |
|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Owner</b>            | City of Rivergate — Department of Public Works, Street Lighting Division                                                                                                                                                              |
| <b>Owner Address</b>    | 500 Rivergate Plaza, Rivergate, CA 91766                                                                                                                                                                                              |
| <b>Property Damaged</b> | One (1) municipal street-light standard (steel mast, ~30 ft) at NE corner of S. Main Street and Third Avenue                                                                                                                          |
| <b>Nature of Damage</b> | Mast bent approximately 40° from vertical at base, luminaire pendant sheared and displaced onto adjacent sidewalk; wiring conduit ruptured at base; power to the fixture out at time of arrival — surrounding pedestrian island unlit |
| <b>Notification</b>     | Rivergate DPW after-hours dispatcher notified 0248 hrs; DPW crew (Unit 7) on scene 0312 hrs to make safe and de-energize feeder                                                                                                       |

**SECTION V — LOCATION / ROADWAY / ENVIRONMENT**

|                                |                                                                                                                                                                                                                          |
|--------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Location Description</b>    | Urban downtown, four-lane divided arterial (two lanes each direction), curbside parallel parking permitted, raised concrete median with landscaped tree wells                                                            |
| <b>Roadway Surface</b>         | Asphalt concrete, dry                                                                                                                                                                                                    |
| <b>Roadway Conditions</b>      | No unusual conditions observed                                                                                                                                                                                           |
| <b>Weather</b>                 | Clear                                                                                                                                                                                                                    |
| <b>Lighting</b>                | Dark — street lighting normally present; the street-light standard at the NE corner of the intersection had been struck and was de-energized (see Section IV). Adjacent block lighting operational.                      |
| <b>Traffic Control Devices</b> | Standard four-phase traffic signal at intersection, functioning at time of collision (fixed cycle, no flash mode); lane striping intact; marked crosswalks on all four legs; posted bus-stop signage and shelter present |
| <b>Visibility Obstructions</b> | None noted for northbound lane approach                                                                                                                                                                                  |

**SECTION VI — COLLISION CLASSIFICATION (CHP 555 CODES)**

|                                               |                                                                                                                            |
|-----------------------------------------------|----------------------------------------------------------------------------------------------------------------------------|
| <b>Primary Collision Factor</b>               | 23153(a) V.C. — Driving Under the Influence Causing Injury (Party 1)                                                       |
| <b>Type of Collision</b>                      | (F) Vehicle vs. Fixed Object AND (G) Vehicle vs. Pedestrian — sequential, single event chain                               |
| <b>Movement Preceding Collision — Party 1</b> | Proceeding straight, then departed marked lane to the right                                                                |
| <b>Movement Preceding Collision — Party 2</b> | Standing at curb (waiting)                                                                                                 |
| <b>Sobriety — Party 1</b>                     | HBD — Under Influence (see narrative)                                                                                      |
| <b>Sobriety — Party 2</b>                     | Not evaluated — pedestrian, no indication of impairment observed by reporting officer                                      |
| <b>Pedestrian Action</b>                      | Not in roadway — standing on sidewalk/bus platform                                                                         |
| <b>Special Information</b>                    | Commercial vehicle involved (transit bus, > 26,000 lb GVWR); passenger-carrying; DUI-arrest secondary to primary collision |

**SECTION VII — SEQUENCE OF EVENTS**

1. Party 1 vehicle (ACID Bus #4177, block 512-OWL) traveling northbound on S. Main Street in the #2 (curb) lane, approaching Third Avenue.
2. Party 1 vehicle departed the marked lane to the right, traversed the parking lane and crossed the north curb face on the east side of S. Main Street approximately 55 feet south of the north curb line of Third Avenue.
3. Right front quarter of Party 1 vehicle struck the base and mid-mast of the City of Rivergate street-light standard at the near-side of the bus-stop platform (see Section IV). Fixture power out following impact.
4. Party 1 vehicle continued forward approximately 22 feet and struck Party 2 (pedestrian Yolanda Reyes), who was standing on the bus-stop concrete pad awaiting service.
5. Party 1 vehicle came to rest at final position — front axle approximately 8 feet beyond the north edge of the bus-stop platform, straddling the curb line, right side against the damaged sign pole of the bus stop.

**SECTION VIII — DIAGRAM OF SCENE (TEXTUAL DESCRIPTION)***Not to scale. North is toward the top of the diagram.*

## TRAFFIC COLLISION REPORT

CHP 555 Format - Local Agency Adaptation Rev. 03-22 OPI 060

**Intersection:** S. Main Street (running north–south) crosses Third Avenue (running east–west) at a signalized four-way intersection with painted crosswalks on all four legs and a raised concrete median on S. Main Street.

**S. Main Street:** Four traffic lanes total (two northbound, two southbound), curbside parallel parking on both sides north of Third Avenue. Lane widths approximately 11 feet; parking lane approximately 8 feet.

**Party 1 path of travel (bus, #4177):** Enters diagram from the south in the northbound #2 (curb) lane. Track shown as a solid line beginning centered in the #2 lane. Approximately 90 feet south of the north curb line of Third Avenue, the track drifts to the right (east). The track crosses the fog line at a point approximately 70 feet south of the north curb line and continues into the parking lane. Two skid/scuff marks observed on the roadway: tire scuff mark #TM-1, right front (14 feet long, curving to the right), and tire scuff mark #TM-2, right rear (11 feet long, parallel offset). No pre-impact braking skid measured.

**Point of impact #1 (POI-1):** Right front bumper of Party 1 vehicle contacts base of street-light standard at NE corner. Standard shown as a circle labeled "SL-1"; deflection arrow points to the northwest, showing mast displacement.

**Point of impact #2 (POI-2):** Approximately 22 feet north of POI-1, at the bus-stop concrete platform (labeled "BS"). Party 2 (labeled "P-2") shown as a stick figure on the platform, near the shelter's south end.

**Rest position of Party 1 vehicle (labeled "V-1 FR"):** Front axle 8 feet beyond north edge of platform, vehicle centerline offset approximately 4 feet east of the original #2 lane centerline, front bearing approximately 015° (magnetic).

**Rest position of Party 2 (labeled "P-2 FR"):** On sidewalk approximately 6 feet north of platform, oriented head-northwest.

**Debris field:** Glass fragments (destination-sign lens), plastic fragments (right mirror housing), and light-standard luminaire remnants distributed between POI-1 and rest position. Blood staining observed on sidewalk between POI-2 and P-2 rest position.

**Signal head:** Signalized intersection to south of scene; NB signal indication was green at reporting officer's arrival and remained on normal cycle throughout scene management.

**Streetlight condition:** SL-1 (impacted standard) — de-energized. Nearest operational streetlights are SL-2 on the SW corner and SL-3 mid-block to the north (both functional).

### SECTION IX — NARRATIVE / STATEMENT OF OPINIONS AND CONCLUSIONS

PAGE 3 of 5 — NARRATIVE

**Notification:** On 10/18/2025 at approximately 0208 hrs, Rivergate PD Communications broadcast a Code 3 call of a traffic collision, bus vs. pedestrian and light pole, at S. Main Street and Third Avenue in downtown Rivergate. Reported controlling time of collision: 02:05 a.m. I, Officer Ramona Delacruz (RPD #2814), was assigned as reporting officer and arrived on scene at 0212 hrs. Rivergate Fire Medic 11 and Medic 14 arrived at 0210 hrs and 0214 hrs respectively.

**Scene on arrival:** I observed a full-size ACTD transit bus (Party 1 vehicle; identified by fleet number 4177 on the front destination panel and rear quarter) at rest on the east side of S. Main Street, north of Third Avenue, with its right front against a bus-stop shelter pole. The right front bumper, sign panel, and forward passenger door frame exhibited fresh impact damage. Approximately 22 feet south of the vehicle's rest position I observed the impacted municipal street-light standard, deflected from vertical, luminaire sheared and lying on the adjacent sidewalk. Ambient overhead illumination at the immediate corner was absent; adjacent-block streetlights were functional. Party 2 (pedestrian, later identified as Yolanda Reyes, DOB 06/22/1991) was being attended by Medic 11 personnel on the sidewalk approximately 6 feet north of the bus-stop platform. Rivergate Fire advised severe multi-system trauma and requested air ambulance. Reach-11 (rotor-wing air ambulance) landed at the pre-designated LZ at Fourth Avenue and Elm Street at 0231 hrs; Party 2 was airlifted from that LZ to Rivergate Regional Trauma Center.

**Party 1 driver contact:** Party 1 driver Raymond T. Keeler was seated in the operator's position of Bus #4177 upon my initial contact at 0213 hrs. He was conscious, alert to person only, and remained belted. I detected the odor of an alcoholic beverage emanating from his breath and person. His eyes were red and watery, his speech was slurred and repetitive, and his balance upon exit was unsteady — he required the vehicle grab bar to steady himself while stepping down. Party 1 stated he "must have dozed" and did not recall the impact sequence. He confirmed his identity, employer, and that he had been on shift since approximately 2200 hrs the prior evening. His California Class B CDL (with passenger endorsement) was produced on request.

**Passengers of Party 1 vehicle:** Three (3) passengers were on board at the time of the collision:

- **Devin Cho** (age 23) — seated in the forward passenger cabin; found lying across the aisle with an obvious deformity of the right lower extremity and brief loss of consciousness reported by fellow passenger Blau. Transported Code 3 by Medic 11 to Rivergate Regional Trauma Center.
- **Alicia Mowbray** (age 40) — seated mid-cabin, port side; complaining of neck, back, and knee pain with visible contusions. Transported Code 2 by Medic 14 to Rivergate Regional Trauma Center.
- **Terrence Blau** (age 30) — seated in the aft cabin; uninjured. Blau stated that Bus #4177 was traveling "at normal speed" northbound and that the operator "just drifted right" without braking. Blau reported observing the light-standard impact first, followed almost immediately by the impact with the pedestrian. Full recorded statement to be taken at RPD Traffic Bureau; contact information

## TRAFFIC COLLISION REPORT

CHP 555 Format - Local Agency Adaptation Rev. 03-22 OPI 060

logged.

**Property damage:** City of Rivergate street-light standard (see Section IV) — mast deflected, luminaire sheared, feeder conduit ruptured; power to the fixture was out on my arrival. Rivergate DPW night dispatcher was notified at 0248 hrs; DPW Unit 7 responded to make safe and de-energize the feeder at 0312 hrs. City claim to be submitted through Rivergate Risk Management.

### Investigation of driver impairment (Party 1):

- Field sobriety tests were attempted at the curb at 0219 hrs. Party 1 exhibited multiple objective signs consistent with alcohol impairment, including horizontal gaze nystagmus (distinct and sustained at maximum deviation in both eyes), inability to maintain the instructional stance during the walk-and-turn (five noted clues), and inability to maintain balance during the one-leg stand (four noted clues).
- Preliminary alcohol screening (PAS/PBT) administered curbside at approximately 0215 hrs on a department-issued Intoximeters Alco-Sensor FST (S/N RPD-AS-0119), calibration current per quarterly log. **Result: 0.11% BrAC.** This is a preliminary breath result and is subject to certified laboratory confirmation.
- Officer's note: preliminary breath result 0.11% — subject to certified evidentiary confirmation.
- Based on the totality of the circumstances — driver's admissions, physical signs, FST performance, and PAS result — I formed the opinion that Party 1 was under the influence of an alcoholic beverage such that he was unable to operate a motor vehicle with the care and caution of a sober person, and further that his condition was a proximate cause of the collision described above.

**Arrest:** Party 1 Raymond T. Keeler was placed under arrest at 0235 hrs at the scene for violation of Vehicle Code § 23153(a) (driving under the influence causing injury). Miranda advisement given at 0236 hrs; Party 1 acknowledged understanding and declined to make further statements. He was informed of the implied-consent obligation under Vehicle Code § 23612 and elected the blood test. Party 1 was transported by Ofc. J. Marquez (RPD #3021) to Rivergate Regional Trauma Center for the evidentiary draw.

**Blood draw:** Evidentiary blood collection was arranged and completed at Rivergate Regional Trauma Center at approximately 0310 hrs by qualified phlebotomist J. Okada (Lic. CPT-1 #C-419887). Two grey-top tubes drawn, sealed, and initialed. Chain-of-custody form RPD-COC-2025-1018-01 initiated at 0316 hrs and specimen booked at RPD evidence locker 0402 hrs pending transfer to the Los Angeles County Sheriff's Department Scientific Services Bureau — Crime Laboratory for analysis. Analytical results pending; lab report will be filed as a supplement upon receipt.

**ACTD notification:** ACTD Dispatch Supervisor W. Tran was notified at 0219 hrs; ACTD field-response supervisor (Unit S-3) arrived on scene at 0304 hrs and coordinated with responding officers regarding vehicle recovery, on-board APC/farebox data preservation, and post-accident DOT testing protocol under 49 CFR Part 655.

**Vehicle disposition:** Bus #4177 was photographed in place, evidence-processed for the collision investigation, and later released to ACTD garage recovery unit at 0525 hrs. Onboard camera/DVR module was tagged at scene at 0341 hrs and released to ACTD Safety representative M. Okonkwo's designee (Field Ops. supervisor) with a data-preservation letter concurrently served on ACTD.

**Injury summary:** One (1) pedestrian severely injured and airlifted (Party 2). Two (2) bus occupants injured and transported (Occ-1 Cho, Occ-2 Mowbray). One (1) bus occupant uninjured and released at scene after statement (Occ-3 Blau). Party 1 driver reported no injuries; medically cleared at Rivergate Regional Trauma Center prior to booking.

### Statements taken at scene:

- Party 1 (Keeler) — brief; substance recorded above; declined further statement post-Miranda.
- Occ-3 (Blau) — brief on-scene statement; contact info logged for follow-up recorded interview at RPD Traffic Bureau.
- No independent civilian witnesses came forward at the scene despite canvass of the surrounding block.

**Photos / evidence:** Digital photographs (72 exposures) taken by reporting officer and Field Evidence Tech M. Cardenas; scene measurements taken via total-station survey conducted by Ofc. K. Ballesteros (RPD #3355) between 0330 hrs and 0455 hrs; measurements filed as Diagram Supplement TC-2025-1018-DS.

## SECTION X — CAUSE / RECOMMENDATIONS

|                                 |                                                                                                           |
|---------------------------------|-----------------------------------------------------------------------------------------------------------|
| <b>Primary Collision Factor</b> | Violation of Vehicle Code § 23153(a) (DUI causing injury) by Party 1, Raymond T. Keeler.                  |
| <b>Party at Fault</b>           | Party 1.                                                                                                  |
| <b>Other Associated Factors</b> | Violation of Vehicle Code § 22107 (unsafe departure from lane of travel), attributed to Party 1.          |
| <b>Party 2 Contribution</b>     | None identified. Party 2 was lawfully standing on the sidewalk / bus-stop platform at the time of impact. |

## TRAFFIC COLLISION REPORT

CHP 555 Format - Local Agency Adaptation Rev. 03-22 OPI 060

|                       |                                                                                                                                                                                                                                                                                                                                                        |
|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Recommendation</b> | Complaint to be forwarded to the Los Angeles County District Attorney's Office for filing consideration under Vehicle Code § 23153(a). Pending items: laboratory analysis of evidentiary blood specimen; supplemental report to include analytical result upon receipt; recorded witness statement of Occupant Blau; total-station diagram supplement. |
|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

### SECTION XI — REPORTING OFFICER CERTIFICATION

I certify (or declare) under penalty of perjury under the laws of the State of California that the foregoing is true and correct to the best of my knowledge and belief, based on my personal observations at the scene, statements taken, and information from officers and personnel assisting in this investigation.

|                                  |                                                       |                              |            |
|----------------------------------|-------------------------------------------------------|------------------------------|------------|
| <b>Reporting Officer (Print)</b> | Ramona Delacruz                                       | <b>Badge / ID No.</b>        | RPD #2814  |
| <b>Assignment</b>                | Patrol, Watch III (Graveyard) / Traffic Investigation | <b>Date</b>                  | 10/18/2025 |
| <b>Signature</b>                 | /s/ Ramona Delacruz                                   | <b>Time Report Completed</b> | 0730 hrs   |
| <b>Reviewed / Approved By</b>    | Sgt. E. Halversen (RPD #1477), Watch Commander        | <b>Date Reviewed</b>         | 10/18/2025 |
| <b>Reviewer Signature</b>        | /s/ E. Halversen                                      |                              |            |

**DISTRIBUTION:** Original — RPD Records; Copy — Traffic Bureau; Copy — LA County DA (upon filing package); Copy — ACTD Risk Management (upon written request); Copy — City of Rivergate Risk Management (property damage).

— END OF REPORT — TC-2025-1018 —