

School	Energy	HVAC	HVAC	HVAC	Building Envelope	Building Envelope	Building Envelope	Building Envelope	Plumbing	Plumbing	Plumbing	Plumbing	Electrical	Electrical	Exterior Wall Integrity	Building Features	Building Features (Historic)	Land Use
	Site Energy Use Intensity (EUI)	Ductwork - Cleaning? When? Some schools have duct work in limited spaces - this reflects school wide ductwork only.	Ceiling Heights	Composite	Windows	Roof Condition - soffit and gutter	Composite	ADA Accessibility	**Plumbing** Plumbing fixtures (sufficient per building code and ADA accessible), and condition of building sprinkler systems.	Existing Condition of Sewer Lines	Existing Condition of Water Lines	Composite	Sufficient power or ability to accommodate additional power, and lighting conditions.	Architect has an electrical engineer - did an evaluation of the electrical capacity to upgrade.	**Exterior Wall Integrity** Condition of the walls, including cracking, settling, sagging, or leaning, and need for tuckpointing.	ADA Accessibility		
School	Utility Reports		Cloor Plans			Hutchinson Roofing Assessment (In process - ratings from previous Divide quotes)		MFP Building Authority	Sewer Scopes (In Process - known issues at Oakton, Orrington, and King Arts)	In Process	In Process	In Process			In Process		In Process	
Documents																		
Bessie Rhodes	50	Needs improvement	Satisfactory	Needs improvement	Satisfactory	Needs improvement	Needs improvement	1-50% Accessible	Needs improvement				Needs improvement	Not Applicable		1-50% Accessible		R1 Zoning (8 pins)
Chute	55.7	Not Applicable	Needs improvement	Unsatisfactory	Satisfactory	Unsatisfactory	Needs improvement	Fully Accessible	Needs improvement				Satisfactory	Not Applicable		Fully Accessible	No	R1 Zoning
Daves	57.3	Not Applicable	Needs improvement	Unsatisfactory	Satisfactory	Satisfactory	Satisfactory	Fully Accessible	Needs improvement				Needs improvement	Not Applicable		Fully Accessible	No	R2 Zoning
Dewey	54.5	Needs improvement	Satisfactory	Needs improvement	Satisfactory	Needs improvement	Needs improvement	70%-99% Accessible	Needs improvement				Satisfactory	Not Applicable		70%-99% Accessible	No	R1 Zoning
JEH Early Childhood	115.5	Needs improvement	Satisfactory	Satisfactory	Satisfactory	Satisfactory	Satisfactory	Fully Accessible	Satisfactory				Satisfactory	Not Applicable		Fully Accessible	No	OS Zoning
Haven	37.5	Not Applicable	Satisfactory	Needs improvement	Excellent	Needs improvement	Needs improvement	Fully Accessible	Needs improvement				Satisfactory	Not Applicable		Fully Accessible	Historic Landmark	R3 Zoning
King Arts	57.7	Not Applicable	Satisfactory	Needs improvement	Satisfactory	Needs improvement	Needs improvement	Fully Accessible	Needs improvement				Satisfactory	Not Applicable		Fully Accessible	No	R2 Zoning
Kingsley	50.5	Needs improvement	Satisfactory	Satisfactory	Satisfactory	Unsatisfactory	Needs improvement	Fully Accessible	Satisfactory				Satisfactory	Not Applicable		Fully Accessible	No	R3 Zoning
Lincoln	49.5	Not Applicable	Satisfactory	Needs improvement	Satisfactory	Needs improvement	Needs improvement	Fully Accessible	Satisfactory				Satisfactory	Not Applicable		Fully Accessible	No	R5 Zoning
Lincolnwood	46.6	Not Applicable	Satisfactory	Needs improvement	Satisfactory	Needs improvement	Needs improvement	1-50% Accessible	Needs improvement				Satisfactory	Not Applicable		1-50% Accessible	No	OS Zoning
Nichols	42.5	Not Applicable	Satisfactory	Needs improvement	Satisfactory	Needs improvement	Needs improvement	Fully Accessible	Needs improvement				Satisfactory	Not Applicable		Fully Accessible	Historic Landmark	R3 Zoning
Oakton	35.7	Not Applicable	Needs improvement	Unsatisfactory	Needs improvement	Needs improvement	Unsatisfactory	1-50% Accessible	Needs improvement				Needs improvement	Not Applicable		1-50% Accessible	Historic Landmark	R2 Zoning
Orrington	47.6	Needs improvement	Needs improvement	Needs improvement	Satisfactory	Unsatisfactory	Unsatisfactory	1-50% Accessible	Needs improvement				Needs improvement	Not Applicable		1-50% Accessible	Historic Landmark	R1 Zoning
Park	50.9	Not Applicable	Needs improvement	Unsatisfactory	Satisfactory	Unsatisfactory	Unsatisfactory	Fully Accessible	Satisfactory				Satisfactory	Not Applicable		Fully Accessible	No	B1 Zoning
Rice																		
Walker	55.6	Not Applicable	Needs improvement	Unsatisfactory	Satisfactory	Unsatisfactory	Needs improvement	51-75% Accessible	Satisfactory				Needs improvement	Not Applicable		51-75% Accessible		R1 Zoning
Washington	65.8	Needs improvement	Needs improvement	Needs improvement	Satisfactory	Unsatisfactory	Needs improvement	70%-99% Accessible	Needs improvement				Needs improvement	Not Applicable		70%-99% Accessible	Historic Landmark	R3 Zoning
Willard	57.4	Not Applicable	Needs improvement	Unsatisfactory	Satisfactory	Needs improvement	Needs improvement	Fully Accessible	Needs improvement				Needs improvement	Not Applicable		Fully Accessible	No	R1 Zoning