VisionInspect AI

Quality Inspection Report

FAILED

Product Information

Inspection ID:	#cfc861c1
Product:	Plastic Part
Product Code:	PP-001
Image Filename:	008.png
Date:	2026-09-10 09:45:39

Defect Analysis

Defect Type:	Contamination
Confidence:	86%
Severity Score:	85.95/100
Severity Level:	Critical
Location (X,Y):	(260, 245)
Size (W×H):	401×407

Image Quality Analysis

Resolution:	900×900 (Good)
Brightness:	135.55 (Good)
Sharpness:	34.24 (Blurry)
Noise:	0.97 (Low)
Overall Quality:	68.1% (Acceptable)

Detection Result Image



Final Recommendation

Reject product. Trigger quality inspection.

Generated on 2026-10-17 19:00:21