VisionInspect AI

Quality Inspection Report

PASS

Product Information

Inspection ID:	#76d2dd90
Product:	Metal Component
Product Code:	MC-001
Image Filename:	000.png
Date:	2026-10-17 16:16:28

No Defect Detected

Product meets all quality standards.

Image Quality Analysis

Resolution:	900×900 (Good)
Brightness:	136.95 (Good)
Sharpness:	39.99 (Blurry)
Noise:	0.97 (Low)
Overall Quality:	68.54% (Acceptable)

Detection Result Image



Final Recommendation

Product meets quality standards.

Generated on 2026-10-18 00:12:45