PRODUCT QUALITY DEFICIENCY REPORT (PQDR)

CATEGORY	REPORT CONTROL NUMBER (RCN)	DATE
☐ I ☐ II	CLM-FT26-008	2026-11-09

1a. FROM *(Original Office Mailing Address - include DoDAAC)*	1b. ORIGINATOR NAME, PHONE NUMBER & E-MAIL ADDRESS
동해기계 / 품질관리팀 사업장 주소: 고객사 등록 정보 참조	고객 품질관리팀 / 연락처: 접수대장 참조
2a. TO *(PQDR Screening Point)*	**2b. SCREENING POINT NAME, TELEPHONE NUMBER & E-MAIL ADDRESS**
청우소재 / 품질보증팀	공급사 품질보증팀 / 연락처: 거래처 등록부 참조

3. DESCRIPTION OF DEFICIENCY (*Describe in detail what is wrong, circumstances prior to the difficulty, probable cause, any action taken, and recommendations. Attach copy of supporting documents. Continue on separate sheet if necessary. Ensure that the description answers the questions listed in the instructions on the back of this form.)*

고객 클레임 접수. 사건 ID: CLM-FT26-008

품번: SD-7108 / 대상 로트: LOT-FT-008 / 증상: 용접부 핀홀

입고 중 발견. 신고 수량 3개. 이번 조치 ID: ACT-FT-008.

원인과 효과는 첨부 조치 기록 및 조치 후 검사 원문으로 확인한다.

접수 파일: 이공공사출생자들_5유형_FT08.pdf

4. DATE DEFICIENCY WAS DISCOVERED

2026-11-08

5. DEFICIENT ITEM NATIONAL STOCK NUMBER (NSN)	6. DEFICIENT ITEM NOMENCLATURE	7. OPERATING TIME AT FAILURE
N/A	스테인리스 배관	☐ Initial Hours: Days: Rounds: Cycles: Miles: Other:

8. DEFICIENT ITEM PART NUMBER	9a. MANUFACTURER'S CAGE CODE	9b. MANUFACTURER / CITY / STATE
SD-7108	N/A	청우소재 / 생산사업장

10. QUANTITY	11. SERIAL, LOT, OR BATCH NUMBER	12a. ITEM	12b. DATE MANUFACTURED, REPAIRED, OR OVERHAULED	12c. LAST REPAIR FACILITY
a. RECEIVED: 100 b. INSPECTED: 100 c. DEFICIENT: 3 d. IN STOCK: 97	SERIAL #: Unknown ☐ LOT #: LOT-FT-008 BATCH #: N/A ☐	☐ New ☐ Repaired ☐ Overhauled ☐ Unknown	Manufactured: Repaired: Overhauled:	CAGE: DODAAC: REPAIR DEPOT / CITY / STATE

13a. CONTRACT NUMBER	13b. REQUISITION / DOCUMENT NUMBER	13c. PURCHASE ORDER NUMBER
	DOC-FT08	PO-FT-008

14. GOVERNMENT FURNISHED MATERIAL	15a. ITEM UNDER WARRANTY	15b. WARRANTY EXPIRATION DATE	16. END ITEM EIC/WUC/TAMCN
☐ YES ☐ NO ☐ UNKNOWN	☐ YES ☐ NO ☐ UNKNOWN		

17. NEXT HIGHER ASSEMBLY

a. NSN	b. NOMENCLATURE	c. PART NUMBER	d. SERIAL NUMBER

18. END ITEM

a. NSN	b. NOMENCLATURE	c. TYPE/MODEL	d. SERIAL NUMBER

19. CURRENT DISPOSITION OF DEFICIENT ITEM (the Exhibit) *(Select only one value)*

☐ HOLDING EXHIBIT ☐ DISPOSED OF / DESTROYED ☐ REPAIRED ☐ OTHER *(Explain in Block 3)*

20. LOCATION OF DEFICIENT MATERIAL (e.g. Base, Camp, Station)

고객 품질관리팀 보관. 관련 검사 기록과 함께 관리.

21. ACTION REQUESTED *(Select only one value)* ☐ REPLACEMENT ☐ REPAIR ☐ CREDIT ☐ OTHER *(Explain in Block 3)*

고객 요청: 첨부 자료를 대조하여 원인 관계와 조치 효과를 검토해 주세요.

제품 식별 라벨

01 사건 ID
CLM-FT26-008

02 품번 / 대상 로트
SD-7108 / LOT-FT-008

03 제품명
스테인리스 배관

04 제조 로트
LOT-FT-008

05 출하일 / 수량
2026-11-07 / 100개

06 라벨 상태
품번과 로트를 현물 표기로 확인

07 발행 부서
청우소재 생산관리팀

과거 8D 리포트

01 과거 사건 ID
HIS-FT-008

02 과거 품번 / 로트
SD-7108 / OLD-008

03 D2 문제 정의
외관 변색

04 D3 임시 봉쇄
대상 로트 격리 및 전수 선별

05 D4 확정 원인
세척액 잔류

06 D5 영구 조치
세척액 교체 및 건조 공정 보완

07 D6 검증 결과서
RES-HIS-FT-008 별첨

08 D7 재발 방지
정기 점검 및 교육 기록 유지

09 D8 종결 기록
과거 조치 당시 품질 담당 검토 완료

10 원인 확인 근거
분해 관찰 및 공정 비교로 해당 원인 확정

과거 조치 결과서

01 관련 과거 사건
HIS-FT-008

02 결과서 ID
RES-HIS-FT-008

03 과거 품번 / 로트
SD-7108 / OLD-008

04 조치 항목
과거 8D D5 기재 조치 이행

05 완료일 / 검사일
2026-09-15 09:00 / 2026-09-15 11:00

06 검사 범위
과거 사건의 신고 불량 계열

07 표본 수 / 불량 수
40개 / 0개

08 기준 / 실측
과거 전용 기준: 불량 수 0개 이하. 실측 0개.

09 유효 범위
위 과거 사건에 한함. 이번 조치 후 검사 기록을 대체하지 않음.

이번 조치 결과서

01 사건 ID
CLM-FT26-008

02 품번 / 대상 로트
SD-7108 / LOT-FT-008

03 이번 조치 ID
ACT-FT-008

04 현상 / 확정 원인
용접부 핀홀 / 용접 보호 가스 유량 저하

05 원인 확인 방법
공정 기록, 현품 관찰 및 원인 재현 시험으로 확인

06 조치 내용
가스 유량계 교정 및 용접부 재작업

07 조치 완료 시각
2026-11-09T09:00:00+09:00

08 효과 확인 연결
INS-FT-008

09 완료 범위
현장 조치 이행 완료. 효과는 별첨 검사 성적서 수치로 확인.

10 작성 부서
청우소재 품질보증팀

검사 기준서

01 검사 기준 ID / 개정

QS-FT-008 / R1

02 적용 대상

SD-7108 전체 로트의 이번 조치 후 검사

03 유효일

2026-01-01부터 유효

04 검사 항목

핀홀

05 합격 조건

핀홀 불량 수 <= 0개

06 최소 표본 수

40개

07 경계값 처리

<= 이므로 상한과 같은 실측값도 허용. 반올림 판정 금지.

08 시점 조건

이번 조치 완료 후 실시한 검사만 유효

조치 후 검사 성적서

01 사건 ID
CLM-FT26-008

02 품번 / 대상 로트
SD-7108 / LOT-FT-008

03 이번 조치 ID
ACT-FT-008

04 검사 ID / 개정
INS-FT-008 / R1

05 검사 시각
2026-11-09T11:00:00+09:00

06 적용 기준
QS-FT-008 R1

07 검사 항목
핀홀

08 표본 수
40개

09 검사 실측
핀홀 불량 수 0개

10 수량 확인
검사 수량은 표본 수와 같음. 불량 수는 이번 조치 후 발생 건수.