

## Defect Record Sheet


<b>A</b>	Defect Ref No : <u>          A          </u>		Date / Time : <u>          1/1/2000          </u>	
	Repeated defect: (Yes/ No) <u>          Yes          </u>			
	Type of Road /Footpath/Facilities : <u>          Flat          </u>			
	Location / Landmark: <u>          WWP LP 2          </u>			
	Type of Asset: <u>          Flat          </u>			
	Description: <u>          ffsafdafasf          </u>			
	Quantity: <u>          1 member          </u>			
	Measurement: <u>          2 member          </u>			
	Cause of Defect: <u>          dsfafasdf          </u>			
	Recommendation: <u>          jrtyhgf          </u>			
	Inspected By : <u>          John1          </u>			
	<u>                                Name                                </u>		<u>                                Signature                                </u>	
	Supervised By : <u>          Tom1          </u>			
	<u>                                Name                                </u>		<u>                                Signature                                </u>	
<b>Defects reported to DRC / RARL / RIA / other agencies on:</b>				
Reported via: <u>          Method / Agency / Date / Time:          </u>				
Acknowledgement: <u>          Method / Date / Time:          </u>				
<b>B</b>	(For LTA Use)			
	Defects Verified by : <u>          Jane1          </u>		<u>          2/2/2004          </u>	
	<u>                                Name                                </u>		<u>                                Signature                                </u>	
	<u>                                Date                                </u>			
<b>C</b>	Instructions: <u>          luyikyjthrgsfdf          </u>			
	WSO No.: <u>          afsdgshryjtrukti          </u>			
<b>C</b>	(For contractor's acknowledgement)			
	Acknowledged and received by: <u>          May1          </u>		<u>          3/3/2004          </u>	
<u>                                Name                                </u>		<u>                                Signature                                </u>		
<u>                                Date                                </u>				
TR322				

## Defect Record Sheet

Location & Photographs

Defect Ref No: SW2-MAS3-EXT-WK004-047

### Sketch



- A** Railing-Damaged  
● LP 25F

### Photographs



TR322

