

Defect Record Sheet


A	Defect Ref No : <u>N-MAS1-EXT-WK082-025</u>		Date / Time : <u>28/03/2024</u>	
	Repeated defect: (Yes/ No) <u>1</u>			
	Type of Road /Footpath/Facilities : <u>Expressway</u>			
	Location / Landmark: <u>Serangoon Road</u> <u>LP001F</u>			
	Type of Asset: <u>drainage</u>			
	Description: <u>Severe defect</u>			
	Quantity: <u>3</u>			
	Measurement: <u>3m x 2m</u>			
	Cause of Defect: <u>Heavy load</u>			
	Recommendation: <u>Seal crack</u>			
	Inspected By : <u>James Lim</u>			
			Name Signature	
	Supervised By : <u>Lily Smith</u>			
			Name Signature	
<p>Defects reported to DRC / RARL / RIA / other agencies on:</p> <p>Reported via: Method / Agency / Date / Time: _____</p> <p>Acknowledgement: Method / Date / Time: _____</p>				
B	(For LTA Use)			
	Defects Verified by : _____			
	Name Signature Date			
	Instructions: _____			
C	WSO No.: _____			
	(For contractor's acknowledgement)			
	Acknowledged and received by: _____			
	Name Signature Date			
TR322				

Defect Record Sheet

Location & Photographs

Defect Ref No: SW2-MAS3-EXT-WK004-047

Sketch



- A** Railing-Damaged
● LP 25F

Photographs



TR322

