N2 schoolhouse: identity is correct, additional material is inconsistent



Q08 internal-stair identity: correct
Fixed relations: 8/8
Registered geometry: PASS
3 full-width blocked surfaces

Internal material is not registered.