

Existing Conditions Report · Cluster B

SYNTHETIC DEMO ? illustrative training case, not an authentic project record.

Purpose and status

SYNTHETIC DEMO ? illustrative training case, not an authentic project record. This PDF is a fabricated baseline report for testing PDF extraction, OCR fallback, and classification. It is not a municipal survey.

Study area

The illustrative study area covers 28 hectares around three retained residential towers, an elevated pedestrian connection, a surface parking court, and a low-lying landscape basin. The baseline assumes a predominantly residential setting with schools, small shops, and community rooms nearby.

Observed conditions

The hypothetical survey records fragmented entrances, poor wayfinding between upper and lower movement levels, uneven lighting, impermeable parking surfaces, and a rainwater low point at the south edge. Existing trees provide strong canopy in some courtyards but weak ecological continuity between blocks.

Evidence gaps

Structural capacity, buried utilities, ownership boundaries, resident preferences, and statutory flood thresholds require confirmation. The report intentionally mixes confident observations with explicit gaps so that a classifier can identify review priority.

Design implication

The baseline supports a repair-and-reconnect concept: prioritise safe entrances and accessible routes, preserve mature canopy, establish a blue-green spine, and test new programme at the street edge before committing to demolition.