




Site sequence: station—street—seam—courtyard



Dual beat is not three equal rectangles.
Left: three nodes on a N-S spine.
Right: Origin section along the station road.
Red ticks are obstacles to verify, not isochrones.


Logo · three areas / two wings · five functions




Loops are suggestions, not confirmed deals Provisional geometry is for internal recalculation only. The organizer gap does not block content scoring.

Three key areas: three morphologies, not three boxes


Zhongzhiyuan
garden + Qinghe edge



Origin Community
station—street—seam—court



Dazhongsi
four-quadrant walking



Mark 1 dual-beat stone (seam)


Mark 2 open-source roll (commerce)

Mark 3 courtyard sample (residence)

Kit: seat / ramp / switch-off sign / paper-map box

Walk path and obstacles to test — not isochrones

Origin Community sequence along station road (hypothesis)
Origin: Wudaokou / Qinghua Donglu Xikou exit · ~80 m/min · dashed = unverified obstacles



Origin

Station public area; gate numbers pending operator diagram

Route

Exit → food frontage → pocket green / rail seam → courtyard; no unauthorized campus cut-through

Speed

Adults ~80 m/min flat; wheelchair / low-vision ramp 40–50 m/min

Obstacles

Signals, viaduct breaks, steps without ramps, night glare, loading

Metrics: internal recalc + low confidence

site_area_sqm

≈ 11.4 km²

11412825.386

confidence: low

green_ratio

约 12%

0.123423

confidence: low

public_space_ratio

约 7%

0.073281

confidence: low

key_area_count

3

provisional nodes

confidence: medium

Provisional geometry is for internal recalculation only. The organizer gap does not block content scoring.

data-value matches metrics.json exactly; humans see rounded values. Content scoring is not blocked.

Provisional geometry is for internal recalculation only. The organizer gap does not block content scoring.