



BECTON DICKINSON (THAILAND) CO.,LTD
24TH FL., THE OFFICES AT CENTRAL WORLD 999/9
RAMA I
PATHUMWAN
BANGKOK
THAILAND
10330
TEL +662 646 1800

Service Report

TO:	FOR:
Kanchana Sonjai Phrachomklao Phetchaburi Hospital 53 Rodfai Rd., T. Klongkrachang Phetchaburi, 76000 032-425505	Work Order Number#: WO-03183247 Case Number#: 02150792

WORK ORDER DETAILS			
Top-Level		Order Type	Preventative Maintenance
Serial Number	E34297300589	Billing Type	Time and Material
Product	342973 - FACSCalibur Cytometer 3 Color Basic IVD	Customer Down	No
Work Order Task Code	T111 Preventive Maintenance		
SERVICE REQUESTED / OBSERVED SYMPTOM / ERROR CODE, BY THE CUSTOMER			
Preventive Services			
IDENTIFIED PROBLEM			
WORK PERFORMED			
PM on plan , check instrument completed , check fluids system pass , check optic system pass , cleaning instrument completed pass , run Nile reds beads check location signal pass , run instrument QC pass , the instrument working normally ,			
PM on plan , the instrument working normally			
PARTS USED			

customer agrees to pay BD's invoice for the services described above at BD's standard rates and subject to BD's standard terms and conditions.