



BECTON DICKINSON (THAILAND) CO.,LTD
24TH FL., THE OFFICES AT CENTRAL WORLD 999/9
RAMA I
PATHUMWAN
BANGKOK
THAILAND
10330
TEL +662 646 1800

Service Report

TO:	FOR:
Kanchana Sonjai Phrachomklao Phetchaburi Hospital 53 Rodfai Rd., T. Klongkrachang Phetchaburi,76000 032-425505	Work Order Number#: WO-03651960 Case Number#: 02494689

WORK ORDER DETAILS			
Top-Level		Order Type	Preventative Maintenance
Serial Number	E34297300589	Billing Type	Time and Material
Product	342973 - FACSCalibur Cytometer 3 Color Basic IVD	Customer Down	No
Work Order Task Code	T111 Preventive Maintenance		
SERVICE REQUESTED / OBSERVED SYMPTOM / ERROR CODE, BY THE CUSTOMER			
Preventive Services			
IDENTIFIED PROBLEM			
WORK PERFORMED			
PM on plan ,check and cleaning instrument completed, check fluids system and sheath pressure 4.5 psi completed pass, check optic and laser system pass, check electronic system pass , run beads location check pass , run FACS comp pass all parameters, the instrument working normally			
PM on plan , the instrument working normally			

Part In	Part Number	Line Qty
---------	-------------	----------

LABOR DETAILS

Activity Type	Start Date And Time	End Date And Time	Total Hours Worked	Total Rounded Hours
PM Labor	10/21/2024 13:24	10/21/2024 17:24	0 day(s) 4 hour(s) 0 minute(s)	4

TRAVEL

Start Date And Time	End Date And Time	Total Hours Work	Total Rounded Hours
10/21/2024 12:25	10/21/2024 13:25	0 day(s) 1 hour(s) 0 minute(s)	1

OTHER EXPENSES	
----------------	--

Expense Type	Line Qty
--------------	----------

DATE: 10/21/2024

Customer Name: Kanchana Sonjai

Customer Signature:

geminis

Customer Signature

Technician: Janboon Pisitpong

Customer Survey

The customer acknowledges that the services described above have been provided to customer's satisfaction. Unless otherwise agreed in a valid agreement between the customer and BD, the customer agrees to pay BD's invoice for the services described above at BD's standard rates and subject to BD's standard terms and conditions.