



BECTON DICKINSON (THAILAND) CO.,LTD
24TH FL., THE OFFICES AT CENTRAL WORLD 999/9
RAMA I
PATHUMWAN
BANGKOK
THAILAND
10330
TEL +662 646 1800

Service Report

TO:	FOR:
Kanchana Sonjai Phrachomklao Phetchaburi Hospital 53 Rodfai Rd., T. Klongkrachang Phetchaburi,76000 032-425505	Work Order Number#: WO-04409562 Case Number#: 03061476

WORK ORDER DETAILS			
Top-Level		Order Type	Preventative Maintenance
Serial Number	E34297300589	Billing Type	Time and Material
Product	342973 - FACSCalibur Cytometer 3 Color Basic IVD	Customer Down	No
Work Order Task Code	T111 Preventive Maintenance		
SERVICE REQUESTED / OBSERVED SYMPTOM / ERROR CODE, BY THE CUSTOMER			
Preventive Services			
IDENTIFIED PROBLEM			
WORK PERFORMED			
PM on plan ,check and cleaning instrument completed, check fluids system and sheath pressure 4.5 psi completed pass, check optic and laser system pass, check electronic system pass , run beads location check pass , run FACS comp pass all parameters, the instrument working normally			
ADDITIONAL COMMENTS FOR SERVICE REPORT			
PM on plan,the instrument working normally			

PARTS USED

Part In	Part Number	Line Qty
---------	-------------	----------

LABOR DETAILS

Activity Type	Start Date And Time	End Date And Time	Total Hours Worked	Total Rounded Hours
PM Labor	11/04/2026 14:40	11/04/2026 18:40	0 day(s) 4 hour(s) 0 minute(s)	4

TRAVEL

Start Date And Time	End Date And Time	Total Hours Work	Total Rounded Hours
11/04/2026 12:40	11/04/2026 14:40	0 day(s) 2 hour(s) 0 minute(s)	2

OTHER EXPENSES

Expense Type	Line Qty
--------------	----------

DATE: 11/06/2026

Customer Name: Kanchana Sonjai

Customer Signature: _____

Technician: Kitpakornkitti Jeeranuch

Customer Survey

The customer acknowledges that the services described above have been provided to customer's satisfaction. Unless otherwise agreed in a valid agreement between the customer and BD, the customer agrees to pay BD's invoice for the services described above at BD's standard rates and subject to BD's standard terms and conditions.