

AIR POLLUTION CONTROL - FIELD INSPECTION WORK SHEET

Key Punch Data:	County	Source	Emission	Action			Data			Agency/
	Number	Number	Point #	Type	Mo	Day	Yr	Indiv. ID		
Line 1	101101	00220	00003	000	121217	12	090678	EE19	1N1	
	1 3	7 8	12 13 15	16 18	52	54	59	66 68	80	
<u>Compliance Status</u>										

Line 2 (Dup. cols. 1-15 from Line 1)

010151	31	101
16 18	78	80

(NOTE: Columns not shown must be left blank)
(Do not punch Line 2 if column 78 is blank)

Company: <u>Martin Marietta Cement</u>	SIC: _____
Address: <u>PO 467, Lyons</u>	County: <u>Boulder</u>
Person Contacted: <u>Gerald Anderson</u>	Phone: _____
Inspected by: <u>Ken Meser</u>	Time: <u>1:30</u> AM/PM

*Routine inspection on Regulation #1
In compliance by inspection.
Entire source showed no violations.*

*Kerogen problem is to be corrected
by combustion by January 1980.*