

Key Punch Data:		County	Source	Emission	Action	Date	Agency/
		Number	Number	Point #	Type	Mo Day Yr	Indiv. ID
1	01101	0220	00003	007	231	062579	1990
1	3	4	7	8	12	13	15
16	18	52	54	59	66	68	80
Compliance Status							

Line 2 (Dup. cols. 1-15 from Line 1)

00151

11

191

16 18

78

80

(NOTE: Columns not shown must be left blank)

(Do not punch Line 2 if column 78 is blank)

Company: Martin Marietta - Quarry SIC: _____

Address: Lyons County: Boulder

Person Contacted: none - see below Phone: _____

Inspected by: M. Parsons Time: 1:15 AM/PM

1. Per passing by observation of rock drill working the upper, southern end of the quarry.
2. Stopped and observed operation.
Track type, remote power (air or electric or hydraulic) rock drill.
3. Saw machine movement and drilling. Some dust, but all 20% opacity or less.
4. Large track type bulldozer working area, little or no dust.