

Key Punch Data:	County Number	Source Number	Emission Point #	Action Type	Date Mo Day Yr	Agency/Indiv. ID
ne 1	101101	0220	00003	0001	1917	1121
	1 3 4	7 8	12 13 15	16 18	52	54 59 66 68 80

Compliance Status

Line 2 (Dup. cols. 1-15 from Line 1)

00151

11

101

16 18

78

80

(NOTE: Columns not shown must be left blank)

(Do not punch Line 2 if column 78 is blank)

Company: Martin Marietta Cement

SIC: _____

Address: Lyons

County: Boulder

Person Contacted: Gerald Anderson

Phone: _____

Inspected by: M Parsons / J. Brower / H. Collier

Time: _____ AM/PM

1. Insp for status, annual insp, final approval.
2. Plant status: Few bugs remaining; overall it looks like the plant is on its way to full operation. The kiln modifications have been pretty well worked out. Problems include pressure differential errors at upper end kiln seal - causing dust leakage. Fuel moisture (coal) content was a problem but is now pretty well resolved (see below). Raw mat'l drier is still under debugging - new bugs (18oz vs 15oz) are due Feb 15. Stick test (per permit) will be done then.

3. Kiln modifications permit - C12,444-2

Final approval inspection:

Coal handling - cooler baghouse burned out twice. Now redesigned, rebuilt. Seems to be ok - emissions 0-10%.

Kiln stack - emissions 0%. operating at 4.2 TPH, 100% coal.

Klinker cooler baghouses - emission 0% from each

Stick test done Oct 20, 1980 by York Res. Copy of report given to H. Collier.

Rec Final approval

COMPLIANCE STATUS CODES	
0 -	Unknown
1 -	Not in Compliance
2 -	In Compliance by Source Test
3 -	In Compliance by Inspection
4 -	In Compliance by Certification
5 -	In Compliance with Increments of Progress
6 -	Not in Compliance with Increments of Progr
7 -	Unknown Compliance with Increments of Progress
8 -	No Applicable State Regulation
9 -	In Compliance -- Closed Down

Calculations attached - based on new permit process rates, inspection
Source in compliance w/ all regs & permit I of P.

Progress
of Progr

ACTION TYPE - DESCRIPTION
12 - Inspection
22 - Source Test
23 - Opacity Observation
24 - Odor Observation

COMPLIANCE STATUS CODES

- 0 - Unknown
- 1 - Not in Compliance
- 2 - In Compliance by Source Test
- 3 - In Compliance by Inspection
- 4 - In Compliance by Certification
- 5 - In Compliance with Increments of Progress
- 6 - Not in Compliance with Increments of Progress
- 7 - Unknown Compliance with Increments of Progress
- 8 - No Applicable State Regulation
- 9 - In Compliance -- Closed Down

3. CALCULATIONS

Source	ACTUAL EM.	ALLOWABLE EM	STATUS
KILN STACK $\phi\phi 1$	see 8-21-80 insp and permit packet C12,444		OK
A-FRAME $\phi\phi 4$	internal baghouses vent inside only outside emission is during baghouse upset or fugitive loss thru mid-dam	R _g 1 IID Fug dust	OK by insp
RAW MAT'L CRUSHERS $\phi\phi 2$	600 tph crushers, baghouse control AP 42 8.19-1, (silo storage) $\text{uncont. } \left\{ \begin{array}{l} 600 \times .1 \text{ lb/ton} = 60 \text{ lb/hr} = \\ 60 \text{ tons/year} @ 8 \text{ hr/day} \\ \text{cont. } \left\{ @ 99\% = .6 \text{ lb/hr} \right. \end{array} \right.$ $\begin{array}{l} 5 \text{ dy/yr} \\ 50 \text{ wt/yr} \end{array}$	R _g 1 IA visible 2% R _g 1 IIC1: 50 lb/hr	OK OK
RAW MAT'L DRYER $\phi\phi 3$	600 tph - baghouse control Pr C12444 Packet - pt 48.4 tpy	R _g 1 IA visible 2% R _g 1 IIC1: 50 lb/hr	OK OK
COAL HANDLING $\phi\phi 6$	56 737 tons/yr processed no stacks	R _g 1 IA R _g 1 IID	OK OK
SITE FD $\phi\phi 5$		R _g 1 IID	OK
QUARRIES $\phi\phi 7$		R _g 1 IID	OK

amp



4.11.11

1.11

1.11.11

AIR POLLUTION CONTROL - FIELD INSPECTION WORK SHEET

Key Punch Data:	County		Source		Emission		Action	Date			Agency/ Indiv. ID					
	Number	Number	Number	Point #	Type	Mo		Day	Yr							
Line 1	0110	0220	00003	0001	0001	0001	0001	09	22	80	0001					
	1	3	4	7	8	12	13	15	16	18	52	54	59	66	68	80

Compliance Status

Line 2 (Dup. cols. 1-15 from Line 1)

000151 01 01 80

(NOTE: Columns not shown must be left blank)
(Do not punch Line 2 if column 78 is blank)

Company: Martin Marietta Cement SIC: _____
 Address: SE of Lyons County: Boulder
 Person Contacted: none Phone: _____
 Inspected by: M. Parsons Time: - AM/PM

1. Aug 21, 1980 msp contained incomplete emission calculations.
Also - process changes at MM (as covered by C 12,444)
require a change in the EMS point source description.

2. EMS now lists:

- 001 CMNT KILN DRYER GRINDER
- 002 PRIMARY & SEC'D CRUSHERS
- 003 HANDLING
- 004 OPEN STORAGE
- 005 BOILER- COAL FIRE STANDBY
- 006 COAL UNLOAD, STORE, CRUSH
- 007 SLATE PIT QUARRY.

Sources now of interest, needing EMS list change to read:

- KILN STACK - main process, baghouse control
- A-FRAME - clinker storage & baghouse control
- RAW MATERIAL CRUSHERS - baghouse control
- RAW MATERIAL DRIER - baghouse control
- COAL HANDLING - unload, (mill) crusher, silo storage
- SITE FUG DUST - water spray control
- QUARRIES A TO F - water truck control

(OVER) ↓

12 - Inspection
22 - Source Test
23 - Opacity Observation
24 - Other Observation

ACTION TYPE - FINAL REVIEW

COMPLIANCE STATUS CODES

0 - Unknown
1 - Not in Compliance
2 - In Compliance by Source Test
3 - In Compliance by Inspection
4 - In Compliance by Certification
5 - In Compliance with Increments of Progress
6 - Not in Compliance with Increments of Progress
7 - Unknown Compliance with Increments of Progress
8 - No Applicable State Regulation
9 - In Compliance -- Closed Down

B. CALCULATIONS

<u>Source</u>	<u>ACTUAL EMISSIONS</u>	<u>ALLOWABLE EMISSIONS</u>	<u>STATUS</u>
KILN STACK ØØ1	see 8-21-80 insp and permit packet C12,444		OK
A-FRAME ØØ4	internal baghouses vent inside only outside emissions is during baghouse upset or Fugitive loss thru mid-door	Rg 1 IID Fug dust	OK by insp
RAW MAT'L CRUSHERS ØØ2	600 tph crushers, baghouse control AP 42 8.19-1 (silo storage) uncert $\begin{cases} 600 \times .1 \text{ lb/ton} = 60 \text{ lb/hr} = \\ 60 \text{ tons/year} @ 8 \text{ hr/day} \\ \text{cost. } \Sigma @ 99\% = .6 \text{ lb/hr} \end{cases}$ 50 tons/yr	Rg 1 IA visible 20% Rg 1 IIC1: 50 lb/hr	OK OK
RAW MAT'L DRYER ØØ3	600 tph - baghouse control Pr C12444 permit - pt 48.4 tpy	Rg 1 IA visible 20% Rg 1 IIC1: 50 lb/hr	OK OK
COAL HANDLING ØØ6	56,737 tons/yr processed no stacks	Rg 1 IA Rg 1 IID	OK OK
SITE FD ØØ5		Rg 1 IID	OK
QUARRIES ØØ7		Rg 1 IID	OK

RECEIVED
JAN 10 1981

ump