INSPECTION REPORT

Property Care Pricing Breakdown & Assessment Report

Property Information

Property Name:	**era villa**
Property Code:	ERA-1772482289
Property Type:	Commercial
Units:	1
Inspector:	Super Administrator
Project Manager:	Project Manager
Inspection Date:	Mar 02, 2026
Completed Date:	Mar 02, 2026 09:18 PM
Status:	Completed

Findings Summary (1 items)

#	Task / Issue	Category	Priority	Labour Hours	Material Cost	Total
1	bathroom	Plumbing	Medium	3.0 hrs	$0.00	**$495.00**
			TOTALS:	**3.0 hrs**	**$0.00**	**$495.00**

CPI Domain Breakdown

Domain #	Domain	Score
1	System Design & Pressure	**2** / 7
2	Material Risk (Supply Lines)	**2** / 5
3	Age & Lifecycle (Use higher of Building vs System)	**1** / 5
4	Access & Containment	**2** / 3
5	Accessibility & Safety (MAX of sub-scores; capped at 4)	**1** / 4
6	Operational Complexity	**0** / 3

Materials Summary (1 items)

#	Material	Qty	Unit	Unit Cost	Line Total	Category
1	bathrooth pipes	2.00	each	$200.00	**$400.00**	Plumbing

#	Material	Qty	Unit	Unit Cost	Line Total	Category
				TOTAL MATERIALS:	$400.00	

Cost Components (Annual)

Base Deployment Cost (BDC)

$8,434.80

Operational baseline

Findings Remediation Labour (FRLC)

$495.00

3.0 hrs @ $165.00/hr

Findings Material Cost (FMC)

$400.00

Materials for remediation

Total Remediation Cost (TRC)

TRC = BDC + FRLC + FMC

Annual: $9,329.80

$777.48 per month

Annual Recurring Price (ARP) & Condition Assessment

ARP (Monthly TRC)

$777.48

Condition Score (from CPI)

67/100

Dual-Gate Tier Assignment

Gate 1: Condition-Based	Gate 2: ARP Cost Pressure	Final Tier (Max)
White-Glove	**Essentials**	**White-Glove**

Final Pricing with Multiplier

ARP × Tier Multiplier (1.35)

$1,049.60

per month

Floor Price: $650.00/month

Inspector Assessment

Notes:

nulll

Recommendations:

null

Risk Summary:

nulll