
Sea Pearl Rescue Boat Repair

Report











Receiving the Rescue boat @

Al Safwan Marine Service Station
















Initial Inspection & Job Assessment 01





Initial Inspection & Job Assessment 02





Initial Inspection & Job Assessment 03















Initial Inspection & Job Assessment 04











Sanding & FRP Job 02





Sanding & FRP Job 03





Painting
















Stencilling, Grabline, Fender Replacement















Delivery

