TENDER DOCUMENT

GRE/ELEC/2026/030

Supply and installation of electrical works at Greenvale Community Hall

Employer: Greenvale Municipality

Synthetic test document - fictional data

Part C1: Tender notice and conditions

The works are located on erf 1042 and the title deed is held by the municipality. Materials for the project are available from suppliers in the district and from the nearest regional centre. The existing electrical installation consists of a main board in the plant room and three sub boards.

The main hall seats about two hundred people and the adjoining rooms are used as classrooms and offices. The site is fenced and has a single vehicle gate on the northern boundary. Electricity is supplied through a metered connection from the municipal network. The existing electrical installation consists of a main board in the plant room and three sub boards. Most of the existing wiring is concealed in the ceiling void and the roof space is accessible through two hatches.

3.3 Tenderers must submit a valid tax compliance status pin issued by the South African Revenue Service.

The community committee reports that the building is busiest on weekday evenings and on Saturdays. Parking for site vehicles is available at the rear of the property near the service entrance. The surrounding properties are residential and the nearest shop is a few hundred metres away. The scope of work covers the main hall, the offices, the passages and the external areas. The employer's agent has prepared the specifications in accordance with standard industry practice.

The building is located in Greenvale and is used throughout the week by community groups. Part C3 describes the extent of the works and the standard of workmanship expected in general terms. The community committee reports that the building is busiest on weekday evenings and on Saturdays. The site is fenced and has a single vehicle gate on the northern boundary.

The kitchen, ablution blocks and storeroom are located on the eastern side of the building. Drawings of the existing layout have been prepared by the employer's agent and are available for inspection. The external areas include a paved forecourt, a small garden and a covered walkway. The surrounding properties are residential and the nearest shop is a few hundred metres away.

An earlier phase of the project was completed on 3 June 2019 and its drawings are held by the employer. The existing electrical installation consists of a main board in the plant room and three sub boards. Parking for site vehicles is available at the rear of the property near the service entrance.

The works are located on erf 1042 and the title deed is held by the municipality. Greenvale Community Hall is a single-storey brick building constructed in 1987 and extended in 2004. Parking for site vehicles is available at the rear of the property near the service entrance. The external areas include a paved forecourt, a small garden and a covered walkway.

The area has a mild climate and rainfall is mostly in the summer months. Greenvale Community Hall is a single-storey brick building constructed in 1987 and extended in 2004. Drawings of the existing layout have been prepared by the employer's agent and are available for inspection. The surrounding properties are residential and the nearest shop is a few hundred metres away.

Electricity is supplied through a metered connection from the municipal network. The municipality has operated the facility since 1996 and the local committee manages bookings. Most of the existing wiring is concealed in the ceiling void and the roof space is accessible through two hatches. Part C3 describes the extent of the works and the standard of workmanship expected in general terms. Drawings of the existing layout have been prepared by the employer's agent and are available for inspection.

The roof is covered with fibre cement sheeting supported on steel trusses. The area has a mild climate and rainfall is mostly in the summer months. The tender documents consist of the invitation, the conditions of tender, the scope of work and the pricing schedule. The community committee reports that the building is busiest on weekday evenings and on Saturdays. The site is fenced and has a single vehicle gate on the northern boundary.

A previous tender for similar works closed on 14 March 2024 and was awarded to a local contractor. The tender documents consist of the invitation, the conditions of tender, the scope of work and the pricing schedule. Materials for the project are available from suppliers in the district and from the nearest regional centre.

The municipality has operated the facility since 1996 and the local committee manages bookings. Electricity is supplied through a metered connection from the municipal network. The surrounding properties are residential and the nearest shop is a few hundred metres away. Existing luminaires in the hall are fluorescent fittings that have reached the end of their service life.

The municipality has operated the facility since 1996 and the local committee manages bookings. The tender documents consist of the invitation, the conditions of tender, the scope of work and the pricing schedule. The kitchen, ablution blocks and storeroom are located on the eastern side of the building.

Drawings of the existing layout have been prepared by the employer's agent and are available for inspection. Materials for the project are available from suppliers in the district and from the nearest regional centre. The scope of work covers the main hall, the offices, the passages and the external areas.

3.7 A certificate of compliance must be handed over to the employer on completion of the works.

The municipality has operated the facility since 1996 and the local committee manages bookings. Part C3 describes the extent of the works and the standard of workmanship expected in general terms. The roof is covered with fibre cement sheeting supported on steel trusses. Materials for the project are available from suppliers in the district and from the nearest regional centre.

3.6 Tenderers must provide a valid letter of good standing issued by the Compensation Fund.

The community committee reports that the building is busiest on weekday evenings and on Saturdays. The external areas include a paved forecourt, a small garden and a covered walkway. The roof is covered with fibre cement sheeting supported on steel trusses. The employer's agent has prepared the specifications in accordance with standard industry practice. Existing luminaires in the hall are fluorescent fittings that have reached the end of their service life.

The employer's agent has prepared the specifications in accordance with standard industry practice. The area has a mild climate and rainfall is mostly in the summer months. A previous renovation replaced the plumbing and the ceiling in the main hall. The scope of work covers the main hall, the offices, the passages and the external areas. The community committee reports that the building is busiest on weekday evenings and on Saturdays.

Materials for the project are available from suppliers in the district and from the nearest regional centre. Part C3 describes the extent of the works and the standard of workmanship expected in general terms. Most of the existing wiring is concealed in the ceiling void and the roof space is accessible through two hatches.

The roof is covered with fibre cement sheeting supported on steel trusses. The works are located on erf 1042 and the title deed is held by the municipality. The employer's agent has prepared the specifications in accordance with standard industry practice.

The existing electrical installation consists of a main board in the plant room and three sub boards. The external areas include a paved forecourt, a small garden and a covered walkway. The main hall seats about two hundred people and the adjoining rooms are used as classrooms and offices. Most of the existing wiring is concealed in the ceiling void and the roof space is accessible through two hatches. Existing luminaires in the hall are fluorescent fittings that have reached the end of their service life.

The works are located on erf 1042 and the title deed is held by the municipality. The surrounding properties are residential and the nearest shop is a few hundred metres away. Most of the existing wiring is concealed in the ceiling void and the roof space is accessible through two hatches. Greenvale Community Hall is a single-storey brick building constructed in 1987 and extended in 2004. Materials for the project are available from suppliers in the district and from the nearest regional centre.

The building is located in Greenvale and is used throughout the week by community groups. The works are located on erf 1042 and the title deed is held by the municipality. A previous renovation replaced the plumbing and the ceiling in the main hall.

3.1 Sealed tenders must be deposited in the tender box at Greenvale Civic Centre, 12 Example Street no later than 11:00 on Monday 25 November 2026.

The works are located on erf 1042 and the title deed is held by the municipality. The scope of work covers the main hall, the offices, the passages and the external areas. A previous renovation replaced the plumbing and the ceiling in the main hall.

The municipality has operated the facility since 1996 and the local committee manages bookings. The kitchen, ablution blocks and storeroom are located on the eastern side of the building. The building is located in Greenvale and is used throughout the week by community groups. Electricity is supplied through a metered connection from the municipal network. The existing electrical installation consists of a main board in the plant room and three sub boards.

The tender documents consist of the invitation, the conditions of tender, the scope of work and the pricing schedule. Part C3 describes the extent of the works and the standard of workmanship expected in general terms. Most of the existing wiring is concealed in the ceiling void and the roof space is accessible through two hatches. Electricity is supplied through a metered connection from the municipal network.

Parking for site vehicles is available at the rear of the property near the service entrance. Part C3 describes the extent of the works and the standard of workmanship expected in general terms. Electricity is supplied through a metered connection from the municipal network.

Greenvale Community Hall is a single-storey brick building constructed in 1987 and extended in 2004. The building is located in Greenvale and is used throughout the week by community groups. The municipality has operated the facility since 1996 and the local committee manages bookings. The scope of work covers the main hall, the offices, the passages and the external areas. Electricity is supplied through a metered connection from the municipal network.

The surrounding properties are residential and the nearest shop is a few hundred metres away. The site is fenced and has a single vehicle gate on the northern boundary. The kitchen, ablution blocks and storeroom are located on the eastern side of the building.

The community committee reports that the building is busiest on weekday evenings and on Saturdays. The roof is covered with fibre cement sheeting supported on steel trusses. The building is located in Greenvale and is used throughout the week by community groups. Greenvale Community Hall is a single-storey brick building constructed in 1987 and extended in 2004.

Existing luminaires in the hall are fluorescent fittings that have reached the end of their service life. The kitchen, ablution blocks and storeroom are located on the eastern side of the building. The existing electrical installation consists of a main board in the plant room and three sub boards.

The surrounding properties are residential and the nearest shop is a few hundred metres away. The employer's agent has prepared the specifications in accordance with standard industry practice. A previous renovation replaced the plumbing and the ceiling in the main hall. The site is fenced and has a single vehicle gate on the northern boundary. Electricity is supplied through a metered connection from the municipal network.

Materials for the project are available from suppliers in the district and from the nearest regional centre. Drawings of the existing layout have been prepared by the employer's agent and are available for inspection. Parking for site vehicles is available at the rear of the property near the service entrance. A previous renovation replaced the plumbing and the ceiling in the main hall. The tender documents consist of the invitation, the conditions of tender, the scope of work and the pricing schedule.

3.2 Only tenderers registered with the Construction Industry Development Board with a contractor grading of 5EP or higher in the electrical engineering works category may submit tenders.

Part C3: Scope of work and conditions of contract

The municipality has operated the facility since 1996 and the local committee manages bookings. Most of the existing wiring is concealed in the ceiling void and the roof space is accessible through two hatches. Greenvale Community Hall is a single-storey brick building constructed in 1987 and extended in 2004. Electricity is supplied through a metered connection from the municipal network. Materials for the project are available from suppliers in the district and from the nearest regional centre.

The site is fenced and has a single vehicle gate on the northern boundary. A previous renovation replaced the plumbing and the ceiling in the main hall. The scope of work covers the main hall, the offices, the passages and the external areas. Most of the existing wiring is concealed in the ceiling void and the roof space is accessible through two hatches. The area has a mild climate and rainfall is mostly in the summer months.

Part C3 describes the extent of the works and the standard of workmanship expected in general terms. The area has a mild climate and rainfall is mostly in the summer months. The kitchen, ablution blocks and storeroom are located on the eastern side of the building. Electricity is supplied through a metered connection from the municipal network. The site is fenced and has a single vehicle gate on the northern boundary.

3.9 A compulsory site inspection and clarification meeting will be held at Greenvale Community Hall on Thursday 5 November 2026 at 09:00, and tenderers who do not attend will be disqualified.

Electricity is supplied through a metered connection from the municipal network. The scope of work covers the main hall, the offices, the passages and the external areas. The external areas include a paved forecourt, a small garden and a covered walkway. Most of the existing wiring is concealed in the ceiling void and the roof space is accessible through two hatches.

The scope of work covers the main hall, the offices, the passages and the external areas. The works are located on erf 1042 and the title deed is held by the municipality. The existing electrical installation consists of a main board in the plant room and three sub boards. The kitchen, ablution blocks and storeroom are located on the eastern side of the building.

The existing electrical installation consists of a main board in the plant room and three sub boards. The employer's agent has prepared the specifications in accordance with standard industry practice. Most of the existing wiring is concealed in the ceiling void and the roof space is accessible through two hatches. Existing luminaires in the hall are fluorescent fittings that have reached the end of their service life. The kitchen, ablution blocks and storeroom are located on the eastern side of the building.

Materials for the project are available from suppliers in the district and from the nearest regional centre. The municipality has operated the facility since 1996 and the local committee manages bookings. Drawings of the existing layout have been prepared by the employer's agent and are available for inspection.

3.4 If preference points are claimed, a certified copy of a valid B-BBEE certificate or sworn affidavit must be submitted.

Materials for the project are available from suppliers in the district and from the nearest regional centre. The site is fenced and has a single vehicle gate on the northern boundary. A previous renovation replaced the plumbing and the ceiling in the main hall. The surrounding properties are residential and the nearest shop is a few hundred metres away. The external areas include a paved forecourt, a small garden and a covered walkway.

Part C3 describes the extent of the works and the standard of workmanship expected in general terms. The main hall seats about two hundred people and the adjoining rooms are used as classrooms and offices. Greenvale Community Hall is a single-storey brick building constructed in 1987 and extended in 2004.

The main hall seats about two hundred people and the adjoining rooms are used as classrooms and offices. The roof is covered with fibre cement sheeting supported on steel trusses. Parking for site vehicles is available at the rear of the property near the service entrance. Drawings of the existing layout have been prepared by the employer's agent and are available for inspection.

3.8 Tenderers must complete the declaration of interest and the declaration of past supply chain management practices.

Most of the existing wiring is concealed in the ceiling void and the roof space is accessible through two hatches. Greenvale Community Hall is a single-storey brick building constructed in 1987 and extended in 2004. Materials for the project are available from suppliers in the district and from the nearest regional centre. The external areas include a paved forecourt, a small garden and a covered walkway.

Electricity is supplied through a metered connection from the municipal network. Existing luminaires in the hall are fluorescent fittings that have reached the end of their service life. A previous renovation replaced the plumbing and the ceiling in the main hall. The community committee reports that the building is busiest on weekday evenings and on Saturdays.

The municipality has operated the facility since 1996 and the local committee manages bookings. Existing luminaires in the hall are fluorescent fittings that have reached the end of their service life. Part C3 describes the extent of the works and the standard of workmanship expected in general terms.

The area has a mild climate and rainfall is mostly in the summer months. A previous renovation replaced the plumbing and the ceiling in the main hall. The surrounding properties are residential and the nearest shop is a few hundred metres away. The main hall seats about two hundred people and the adjoining rooms are used as classrooms and offices.

Parking for site vehicles is available at the rear of the property near the service entrance. Materials for the project are available from suppliers in the district and from the nearest regional centre. The site is fenced and has a single vehicle gate on the northern boundary.

Most of the existing wiring is concealed in the ceiling void and the roof space is accessible through two hatches. The scope of work covers the main hall, the offices, the passages and the external areas. The existing electrical installation consists of a main board in the plant room and three sub boards.

The tender documents consist of the invitation, the conditions of tender, the scope of work and the pricing schedule. Existing luminaires in the hall are fluorescent fittings that have reached the end of their service life. Most of the existing wiring is concealed in the ceiling void and the roof space is accessible through two hatches. The community committee reports that the building is busiest on weekday evenings and on Saturdays.

The employer's agent has prepared the specifications in accordance with standard industry practice. The municipality has operated the facility since 1996 and the local committee manages bookings. Most of the existing wiring is concealed in the ceiling void and the roof space is accessible through two hatches. The roof is covered with fibre cement sheeting supported on steel trusses.

The existing electrical installation consists of a main board in the plant room and three sub boards. The municipality has operated the facility since 1996 and the local committee manages bookings. The building is located in Greenvale and is used throughout the week by community groups. Parking for site vehicles is available at the rear of the property near the service entrance. Greenvale Community Hall is a single-storey brick building constructed in 1987 and extended in 2004.

The works are located on erf 1042 and the title deed is held by the municipality. The area has a mild climate and rainfall is mostly in the summer months. The external areas include a paved forecourt, a small garden and a covered walkway. The municipality has operated the facility since 1996 and the local committee manages bookings.

The building is located in Greenvale and is used throughout the week by community groups. A previous renovation replaced the plumbing and the ceiling in the main hall. The existing electrical installation consists of a main board in the plant room and three sub boards. Electricity is supplied through a metered connection from the municipal network.

The scope of work covers the main hall, the offices, the passages and the external areas. The employer's agent has prepared the specifications in accordance with standard industry practice. The surrounding properties are residential and the nearest shop is a few hundred metres away.

The surrounding properties are residential and the nearest shop is a few hundred metres away. A previous renovation replaced the plumbing and the ceiling in the main hall. The employer's agent has prepared the specifications in accordance with standard industry practice. The municipality has operated the facility since 1996 and the local committee manages bookings.

3.5 A certified copy of the company registration certificate must be included in the tender submission.

The employer's agent has prepared the specifications in accordance with standard industry practice. The kitchen, ablution blocks and storeroom are located on the eastern side of the building. The main hall seats about two hundred people and the adjoining rooms are used as classrooms and offices. The tender documents consist of the invitation, the conditions of tender, the scope of work and the pricing schedule.

Drawings of the existing layout have been prepared by the employer's agent and are available for inspection. A previous renovation replaced the plumbing and the ceiling in the main hall. Part C3 describes the extent of the works and the standard of workmanship expected in general terms. Electricity is supplied through a metered connection from the municipal network. The external areas include a paved forecourt, a small garden and a covered walkway.

The employer's agent has prepared the specifications in accordance with standard industry practice. The municipality has operated the facility since 1996 and the local committee manages bookings. The building is located in Greenvale and is used throughout the week by community groups.

Part C3 describes the extent of the works and the standard of workmanship expected in general terms. Materials for the project are available from suppliers in the district and from the nearest regional centre. Parking for site vehicles is available at the rear of the property near the service entrance. The municipality has operated the facility since 1996 and the local committee manages bookings. The site is fenced and has a single vehicle gate on the northern boundary.

Parking for site vehicles is available at the rear of the property near the service entrance. The area has a mild climate and rainfall is mostly in the summer months. Materials for the project are available from suppliers in the district and from the nearest regional centre.

Meetings of the evaluation committee are held at the civic centre and the minutes are kept by the supply chain office. A previous renovation replaced the plumbing and the ceiling in the main hall. The kitchen, ablution blocks and storeroom are located on the eastern side of the building.

The scope of work covers the main hall, the offices, the passages and the external areas. Electricity is supplied through a metered connection from the municipal network. A previous renovation replaced the plumbing and the ceiling in the main hall. The building is located in Greenvale and is used throughout the week by community groups. The tender documents consist of the invitation, the conditions of tender, the scope of work and the pricing schedule.

The scope of work covers the main hall, the offices, the passages and the external areas. The external areas include a paved forecourt, a small garden and a covered walkway. Part C3 describes the extent of the works and the standard of workmanship expected in general terms.

Part C2: Pricing data - Bill of Quantities

Rates and amounts are to be completed by the tenderer.

Item	Description	Unit	Qty	Rate	Amount
SECTION: PRELIMINARIES AND GENERAL					
A1	Health and safety plan and file	sum	1		
A2	Insurance and guarantees	sum	1		
SECTION: DISTRIBUTION BOARDS					
B1	Miniature circuit breaker, 3-pole, 63 A, 10 kA	no	14		
B2	Surge protection device, type 2, 3-phase	no	1		
SECTION: CONTAINMENT					
C1	PVC conduit, 20 mm, surface mounted	m	1073		
SECTION: CABLES					
D1	2-core 2.5 mm2 PVC insulated copper cable, installed in conduit	m	359		
D2	2-core 4 mm2 PVC insulated copper cable, installed in conduit	m	1065		
D3	2-core 6 mm2 PVC insulated copper cable, installed in conduit	m	243		
D4	2-core 10 mm2 PVC insulated copper cable, installed in conduit	m	862		
D5	3-core 1.5 mm2 PVC insulated copper cable, installed in conduit	m	1122		
D6	3-core 6 mm2 PVC insulated copper cable, installed in conduit	m	1149		
D7	3-core 16 mm2 PVC insulated copper cable, installed in conduit	m	283		
D8	4-core 4 mm2 PVC insulated copper cable, installed in conduit	m	980		
D9	4-core 10 mm2 PVC insulated copper cable, installed in conduit	m	806		
D10	4-core 16 mm2 PVC insulated copper cable, installed in conduit	m	415		
SECTION: SMALL POWER					
E1	Double switched socket outlet, 16 A	no	134		
SECTION: EARTHING AND TESTING					
F1	Earth rod, copper clad, 1.5 m	no	11		
F2	Bare copper earth conductor, 16 mm2	m	113		