

Inspection Report

Date: 18.06.2026

Robot: TestBot

Task: Anomaly Detection (Red belt)

Requested by: Tester

Tiles inspected: 4

OK: 3 **DEFECT:** 1

Tile ID	Status	Defect ratio
0	OK	0.000
1	OK	0.000
2	OK	0.000
3	DEFECT	0.050

ID: 3


