

Inspection Report

Date: 19.06.2026
Robot: Megatron

Task: Ring Counting

Requested by: Anita
Total rings detected: 3

Detected colours:

Colour	Count
Blue	1
Green	1
Red	1

Task: Anomaly Detection (Red belt)

Requested by: Fred
Tiles inspected: 4
OK: 1 DEFECT: 2

Tile ID	Status	Defect ratio
0	DEFECT	0.047
1	OK	0.000
2	DEFECT	0.019
3	UNKNOWN	0.000

ID: 0



ID: 2

