LIFT SERVICE REPORT

01 REPORT & BUILDING DETAILS

Report No.: 1	Date: 08/10/2026
Building: ABC Apartment (sample)	Location: Pune, Maharashtra
Lift quantity: 1	Service month: OCT 2026
Lift serviced: 08/10/2026	Service person: _____

02 BASIC SERVICE CHECKLIST

Inspection point	Status	Remarks
Door operation	☒ OK	-
Lift running / leveling	☒ OK	-
Machine / motor	☒ OK	-
Safety devices	☒ OK	-
Car lighting / fan	☒ OK	-

03 WORK DONE / REMARKS

Routine maintenance completed. Door operation checked, moving parts inspected, and lift operation tested.

04 LIFT STATUS & NEXT VISIT

Lift status: Working Satisfactorily	Next service month: NOV 2026

05 ACKNOWLEDGEMENT

SERVICE PERSON	CUSTOMER / REPRESENTATIVE
Name: _____	Name: _____
Signature: _____	Signature: _____