

# Inspection Report

**Report ID: RPT-2025-09-30-A75C86**

## Inspected Item

Damage Type: Rust  
Severity: Low  
Action Required: Monitor  
Inspector Name: test  
Inspector Id: test  
Vendor: test  
Batch: test  
Location: test  
Rid: RID002  
Timestamp: 2025-09-30T10:16:34.349320  
Photo Filename: None

## AI Analysis

Condition Score: 90  
Predicted Failure Risk: Low risk of failure within 12 months  
Vendor Score: No vendor alert

## Work Order

Priority Level: Low  
Action: Monitor  
Spare Part Sku: NUT-M8-B  
Assigned To: Jaipur Maintenance Division  
Status: Pending

## Supervisor Approval

Supervisor Signature:  
Date: None