

Inspection Report: RPT-2025-09-30-66C3B3

Inspected Item:

damage_type: Rust
severity: Low
action_required: Monitor
inspector_name: test
inspector_id: test
vendor: test
batch: twst
location: test
rid: RID001
timestamp: 2025-09-30T09:29:13.209481
photo_filename: None

AI Analysis:

condition_score: 90
predicted_failure_risk: Low risk of failure within 12 months
vendor_score: No vendor alert

Work Order:

priority_level: Low
action: Monitor
spare_part_sku: NUT-M8-B
assigned_to: Jaipur Maintenance Division
status: Pending

Supervisor Approval:

Supervisor Signature: _____

Date: 2025-09-30