

Inspection Report: RPT-2025-09-29-B2CC05

Inspected Item:

damage_type: Rust
severity: Low
action_required: Monitor
inspector_name: test
inspector_id: test
vendor: test
batch: test
location: test
rid: RID003
timestamp: 2025-09-29T21:01:54.583290
photo_filename: None

AI Analysis:

condition_score: 90
predicted_failure_risk: Low risk of failure within 12 months
vendor_score: No vendor alert

Work Order:

priority_level: Low
action: Monitor
spare_part_sku: NUT-M8-B
assigned_to: Jaipur Maintenance Division
status: Pending

Supervisor Approval:

Supervisor Signature: _____
Date: 2025-09-29