

Inspection Report

Report ID: RPT-2025-09-30-5E7F39

Inspected Item

Damage Type: Rust

Severity: Low

Action Required: Monitor

Inspector Name: test

Inspector Id: test


Vendor: test

Batch: test

Location: test

Rid: RID002

Timestamp: 2025-09-30T10:17:43.274368



AI Analysis

Condition Score: 90

Predicted Failure Risk: Low risk of failure within 12 months

Vendor Score: No vendor alert

Work Order

Priority Level: Low

Action: Monitor

Spare Part Sku: NUT-M8-B

Assigned To: Jaipur Maintenance Division

Status: Pending

Supervisor Approval

Supervisor Signature:

Date: None