

# Inspection Report: RPT-2025-09-30-DFAB68

## Inspected Item:

damage\_type: Rust  
severity: Low  
action\_required: Monitor  
inspector\_name: test  
inspector\_id: test  
vendor: test  
batch: test  
location: test  
rid: RID001  
timestamp: 2025-09-30T09:22:13.003367  
photo\_filename: None

## AI Analysis:

condition\_score: 90  
predicted\_failure\_risk: Low risk of failure within 12 months  
vendor\_score: No vendor alert

## Work Order:

priority\_level: Low  
action: Monitor  
spare\_part\_sku: NUT-M8-B  
assigned\_to: Jaipur Maintenance Division  
status: Pending

## Supervisor Approval:

Supervisor Signature: \_\_\_\_\_

Date: 2025-09-30