

Inspection Report

Report ID: RPT-2025-09-30-9F371F

Inspected Item

Damage Type: Rust
Severity: Low
Action Required: Monitor
Inspector Name: test
Inspector Id: test
Vendor: test
Batch: test
Location: test
Rid: RID002
Timestamp: 2025-09-30T10:21:19.145851



AI Analysis

Condition Score: 90
Predicted Failure Risk: Low risk of failure within 12 months
Vendor Score: No vendor alert

Work Order

Priority Level: Low
Action: Monitor
Spare Part Sku: NUT-M8-B
Assigned To: Jaipur Maintenance Division
Status: Pending

Supervisor Approval

Supervisor Signature:
Date: None