




	Index	FileName	Orientation	Width	Instance	Image
0	0	diagonal2.png	Diagonal	4.46	1	 A photograph of a light-colored, textured surface with a prominent diagonal crack running from the top-left towards the bottom-right. The crack is highlighted with a green outline, and a red rectangular bounding box is drawn around it. A small red label in the top-left corner of the bounding box reads "crack 0.75".
1	1	vertical.jpg	Vertical	2.42	1	 A photograph of a light-colored, textured surface with a vertical crack running from the top towards the bottom. The crack is highlighted with a green outline, and a red rectangular bounding box is drawn around it. A small red label in the top-left corner of the bounding box reads "crack 0.75".
2	2	horizontal2.jpg	Horizontal	7.73	1	 A photograph of a light-colored, textured surface with a horizontal crack running across the middle. The crack is highlighted with a green outline, and a red rectangular bounding box is drawn around it. A small red label in the top-left corner of the bounding box reads "crack 0.78".