

AutoScope: AI-Powered Car Condition Reports



Overview/Briefing Document

Summer 2025

1. The Problem

The used car market is riddled with uncertainty. Private sellers struggle to gain trust, and buyers often make risky purchases based on limited photos and vague descriptions. While platforms like Carfax provide vehicle history, they rely on past data and don't evaluate the vehicle's current physical condition. Traditional inspections are expensive and slow, leaving a gap for fast, affordable, and AI-driven tools.

2. The Solution: AutoScope

AutoScope is a mobile-first tool that uses AI to generate car condition reports in seconds. Users upload images of their car and input a VIN. Our system analyzes the photos, pulls key data from public databases, and delivers a professional PDF report that's easy to share in listings.

3. Why This is a Smart Investment

- The U.S. used car market exceeds \$800B annually.
- First-mover advantage in accessible, AI-powered visual inspections for consumers.
- Clear monetization: pay-per-report, monthly subscriptions for dealers/flippers, or white-label for marketplaces.
- Clear area for growth: not only does AutoScope itself a great product, it's a great business with many other additional applications that can be added as the business grows.

4. Why We're Better Than the Competition

- Carfax: Provides vehicle history and can be used by private sellers, but does not analyze current car condition based on photos, strictly based on the history (of what's been reported).
- AutoCheck: AutoCheck focuses on historical data like title records, accidents, and odometer readings. While not an AI inspection tool, it's often used alongside physical inspections to verify a car's background.
- Cars.com: "Great Deal" or "Good Buy" is not fooling anyone, just because a seller simply pays for a label on their listing, does not mean the car is more likely to sell.
- AutoScope: Built for everyday car sellers and flippers. It's mobile-first, photo-based, and instant—no hardware or dealership needed.

5. Why AutoScope is Valuable for Private Sellers

If you're a regular person trying to sell your car, you want to stand out in a crowded online marketplace. Buyers are skeptical—especially when they're spending thousands. AutoScope gives sellers a quick, low-cost way to boost buyer confidence.

- Makes your listing look more trustworthy
- Saves you the hassle and cost of third-party inspections
- Can help you justify your asking price
- Gives buyers peace of mind before even showing up

Think of it like a Carfax for what your car looks like *today*, rather than strictly the history of it. In a world where trust sells, AutoScope helps you close the deal faster.

6. VIN Inspection + Vehicle History Report

The VIN Inspection feature within AutoScope goes beyond basic decoding. It provides users with a full vehicle history snapshot to help them make more informed decisions when buying or selling a car.

****Included in the VIN Report:****

- Year, Make, Model, Engine, Transmission
- Body Style & Country of Origin
- ****Accident History**** (from public records and insurance databases)
- ****Title Checks**** (salvage, rebuilt, flood, etc.)
- ****Odometer Verification****
- ****Service Records**** (dealership or major repair logs)
- ****Recall Status****
- ****Previous Use**** (fleet, rental, lease, personal)

This expanded report transforms AutoScope into a trusted alternative to Carfax or AutoCheck for independent sellers and buyers — all integrated within the same inspection flow.

7. App Mockups (Visual Concepts)

The following pages will include visual mockups of:

- VIN & Photo Submission Screen
- Report Preview
- Final PDF-Style Report

Photos here:

1:51



AutoScope Home



Welcome to
AutoScope

Upload photos of your vehicle and VIN to
recieve a condition report scored by AI



AutoScope Home



AI Condition Report



Reports

1:51

50



AutoScope Home

Upload photos of your vehicle and VIN to
recieve a condition report scored by AI



THE FUTURE OF BUYING AND SELLING CARS STARTS NOW



Start my Report!



AutoScope Home



AI Condition Report



Reports

1:51



AI Condition Report

Fill out an AutoScope Report below!

Vehicle Name

Your Email Address

Vehicle VIN #

Front Image



Choose an image...

Rear Image



Choose an image...



AutoScope Home



AI Condition Report



Reports

1:51

50



AI Condition Report

Rear Image



Choose an image...

Driver Side Image



Choose an image...

Passenger Side Image



Choose an image...

Interior Image



Choose an image...

Front Driver Side Tire



Choose an image...

Rear Driver Side Tire



Choose an image...

Front Passenger Side Tire



AutoScope Home



AI Condition Report



Reports

1:51

50



AI Condition Report

Front Passenger Side Tire



Choose an image...

Rear Passenger Side Tire



Choose an image...

Front Driver Side Rim



Choose an image...

Rear Driver Side Rim



Choose an image...

Front Passenger Side Rim



Choose an image...

Rear Passenger Side Rim



Choose an image...

Submitted At



AutoScope Home



AI Condition Report



Reports

1:51

50



AI Condition Report

 Choose an image...

Front Driver Side Rim

 Choose an image...

Rear Driver Side Rim

 Choose an image...

Front Passenger Side Rim

 Choose an image...

Rear Passenger Side Rim

 Choose an image...

Submitted At



Submit



AutoScope Home



AI Condition Report



Reports

1:51

50



Tap on Finished Report Below!

Search



Zach
Brjdjdhe



AutoScope Home



AI Condition Report



Reports

1:51



Zach

Brjdjdhe

 Edit

Email

@email

Report Type

Basic

Rear Image



AutoScope Home



AI Condition Report



Reports

1:51

50



Zach

Edit

Email

@email

Report Type

Basic

Rear Image



Side Image



Interior Image



Tires Image



Submitted At

July 8, 2025 at 5:25 PM



AutoScope Home



AI Condition Report



Reports

9:41



Damage Details



Zach

Brigidhe



Overall Score

Front bumper
(Minor scratches)

Damage Details



Front passenger

Front passenger

Results

1HGBH41JXMN109186



2017 Toyota Camry



Accident History

1 Record



Odometer Check

No Issues



Service Records

12 Records



Title Check

No Issues



Usage

Personal

Share Your AI Condition Report?



Share via Email



Open in PDF



AutoScope Vehicle Condition Report

Client Name: Honda Civic R

Vehicle VIN #: Hdhdebd

Date Submitted: 2025-07-11T13:27:00.000Z

Front of Vehicle

The image shows a vehicle from the front perspective. The front bumper appears intact with no visible cracks or dents. The grille is in place and retains its shape without any noticeable damage. The headlights are clear and seem to be functioning correctly, with no visible cracks or moisture inside. The hood appears to be aligned properly, with no signs of warping or misalignment. The windshield is clean and free from cracks or chips. Overall, the front of the vehicle appears in good condition, showing no significant signs of damage or misalignment.

Rear of Vehicle

The image of the rear of the vehicle shows the following observations:

- ****Trunk Lid**:** The trunk lid appears to be in good condition with no visible cracks or dents. The emblem is intact, and the surface looks smooth.
- ****Rear Bumper**:** The rear bumper also seems undamaged. There are no noticeable scratches, dents, or alignment issues. The paint is uniform, and the contours appear consistent with the vehicle's design.
- ****Taillights**:** Both taillights are intact without any cracks or breaks. The lights seem to be properly aligned within their housings.

- ****License Plate Area****: The area around the license plate looks clean, with no signs of damage surrounding the plate mount. The plate itself is secure and positioned appropriately.

- ****Exhaust Pipes****: The exhaust pipes show no signs of damage or misalignment. They appear to be properly attached and in good visual condition.

Overall, the rear of the vehicle presents itself as well-maintained with no apparent visible damage or issues.

Driver Side

The image shows significant damage on the driver's side of the vehicle.

1. ****Driver-Side Door****: The driver-side door appears severely crumpled and distorted, with noticeable panel deformation that compromises its structural integrity.
2. ****Quarter Panel****: The quarter panel shows extensive damage, including a deep dent and paint scuffs. The metal is bent and warped severely.
3. ****Side Mirror****: The side mirror is intact, but there are signs of scratches or paint transfer on the surface.
4. ****Rocker Panel Area****: The rocker panel is visibly damaged, with crumpling observable and some exposed metal due to paint loss.

Overall, the damage is extensive on the driver's side, indicating a serious impact.

Passenger Side

There are a few minor imperfections in the paint, but overall the passenger side appears to be in good condition. Panels look properly aligned and there are no major dents or visible damage.

Wheel Condition

Front Driver Side Wheel:

The Front Driver Side Rim appears to be in good cosmetic condition. There are no visible signs of curb rash, corrosion, bends, or scratches on the rim. The black finish looks uniform and well-maintained, indicating proper care. The design is sharp and sporty, which is characteristic

of aftermarket wheels, though they could also be factory-standard depending on the specific vehicle model. Overall, the rim contributes to the overall aesthetic of the car without any noticeable blemishes.

Rear Driver Side Wheel:

The Rear Driver Side Rim appears to be in excellent cosmetic condition. There are no visible signs of curb rash, corrosion, or bends on the rim. The surface looks clean and well-maintained, with no noticeable scratches.

The rim design suggests an aggressive, sporty aesthetic, characteristic of aftermarket wheels, but it may also be a factory-standard design depending on the vehicle model. Overall, the rim presents a polished and sharp appearance that enhances the vehicle's look.

Front Passenger Side Wheel:

The Front Passenger Side Rim shows a sleek, multi-spoke design, typical of aftermarket or sport-oriented wheels. The finish appears to be in good condition, with no visible signs of curb rash, corrosion, or major scratches on the rim itself. The surface is clean, indicating proper maintenance. The brake caliper is painted red, which adds a sporty aesthetic that complements the rim's overall look. The tire also appears to have sufficient tread depth, suggesting it is in usable condition. Overall, the cosmetic condition of the rim appears to be excellent and well-maintained.

Rear Passenger Side Wheel:

The Rear Passenger Side Rim appears to be in good cosmetic condition overall.

- ****Curb Rash****: There are minor signs of curb rash visible on the outer edge of the rim. It is slight but noticeable and suggests that the rim has made contact with a curb.

- ****Corrosion****: There is no visible corrosion on the rim. The surface looks clean and well-maintained, without any discoloration or rust.

- ****Bends****: No bends are noted in the rim; it appears to maintain its standard shape without any deformities.

- ****Scratches****: Apart from the minor curb rash, there appear to be light scratches on the surface, but they are not deep or extensive.

Regarding the design, the rim appears to be a factory-standard type rather than an aftermarket option, given its styling and finish.

In summary, while the rim shows some signs of wear, particularly from curb contact, it remains in decent condition, with no significant damages affecting its functionality.

Tire Condition

Front Driver Side Tire:

The Front Driver Side Tire in the image shows several key characteristics:

1. ****Tread Depth****: The tread appears to be significantly worn, with limited depth remaining. The wear indicators may be visible or the overall height of the tread suggests a level that could be approaching the minimum required for safe traction.
2. ****Wear Pattern****: The wear appears uneven, with a noticeable flattening of the tread. This could indicate possible misalignment or improper inflation levels over time.
3. ****Visible Signs****: There are some areas on the sidewall with potential early signs of cracking, although they are not extensive. There are no obvious signs of balding, but the reduced tread height suggests that grip may be compromised.

Based on these observations, the tire appears to be in ****poor condition**** and may not be safe for continued use without inspection or replacement. It is advisable to have this tire evaluated by a professional to ensure safety and performance.

Rear Driver Side Tire:

The Rear Driver Side Tire shows significant wear. The tread depth appears low, indicating that the tire is nearing the end of its usable life.

1. ****Tread Depth****: The tread is worn down substantially, with minimal patterns visible, which points to inadequate grip.
2. ****Wear Pattern****: There is uneven wear along the tire, which may suggest misalignment or improper inflation.
3. ****Visible Signs****: Cracking is visible along the sidewall, indicating potential structural weakness. There are also signs of balding, particularly in the center of the tread.

Given these observations, the tire appears to be in poor condition and not safe for continued use. Immediate replacement is recommended to ensure safety.

Front Passenger Side Tire:

The Front Passenger Side Tire appears to have visible tread depth and a recognizable tread pattern, indicating that it is not completely bald. However, there are some noticeable signs of wear, such as:

1. ****Tread Depth****: The tread seems to be wearing down, but not to a concerning level. There is still sufficient tread present for grip in normal conditions, although closer inspection would be needed to quantify the exact depth.
2. ****Wear Pattern****: The wear appears somewhat uniform across the tread. However, there are signs of irregularities at certain sections, suggesting that there may be uneven wear, potentially indicating issues such as improper alignment or inflation.

characters.
worn, with limited depth remaining. The
tread suggests a level that could be

3. ****Signs of Balding****: There are no clear indications of significant balding, but the wear patterns suggest that continuous monitoring may be beneficial.

4. ****Cracking****: The sidewall does show small cracks, which could be a concern as they may worsen over time or with further exposure to use.

Overall, the tire is showing signs of wear but is not in poor condition yet. It is advisable to regularly monitor this tire, considering the visible signs of cracking and the uneven wear patterns. Regular maintenance, such as checking alignment and inflation, will help extend its lifespan and maintain safety.

Rear Passenger Side Tire:

The image of the Rear Passenger Side Tire shows significant wear and deterioration.

1. ****Tread Depth****: The tread appears to be considerably worn down, suggesting it is nearing the minimum recommended depth for safe driving.

2. ****Wear Pattern****: There are signs of uneven wear, particularly on the outer edge of the tire, which indicates potential misalignment or pressure issues.

3. ****Balding****: The tire displays areas that are nearly bald, especially along the side close to the rim, which raises concerns about traction and safety.

4. ****Cracking****: There are visible cracks along the sidewall, which can lead to potential blowouts and indicate aging or damage.

Based on these observations, the Rear Passenger Side Tire is in poor condition and may not be safe for continued use. Immediate replacement or professional evaluation is recommended to ensure vehicle safety.

Interior Condition

The interior of the vehicle presents a visually striking combination of red and black materials that give it a sporty ambiance.

Seats:

- ****Condition****: The seats are primarily covered in a combination of red fabric and black suede-like material.

- ****Tears/Stains****: There are no visible tears or stains noted on the seats; they appear clean and well-maintained.

- ****Wear****: Minimal wear is evident; the fabric appears vibrant without any significant fading.

Dashboard:

- ****Condition****: The dashboard has a sleek design, primarily black with some metallic accents.
- ****Cracks****: No visible cracks are observed, maintaining a polished look.
- ****Components****: The dashboard houses various buttons and displays, none of which appear damaged.

Steering Wheel:

- ****Condition****: The steering wheel is well-shaped and appears free of any wear marks.
- ****Missing Parts****: All necessary controls and logos are intact, with no missing components.

Center Console:

- ****Condition****: The center console is primarily black with a user-friendly layout.
- ****Tears/Stains****: No stains are present, and it appears to be in excellent condition.
- ****Components****: Gear shifter, cup holders, and controls all seem to be operational with no signs of damage.

Flooring:

- ****Condition****: The flooring appears clean and well-kept, with a slight glow from ambient lighting.
- ****Wear****: There is no visible wear or stains on the flooring, indicating it has been protected and is in good condition.

Overall Components:

- ****Ambient Lighting****: The interior features ambient red lighting, enhancing the sporty character while also illuminating the floor.
- ****Pedals****: Pedals are visible with no signs of excessive wear, ensuring they are functional.

In conclusion, the interior of the vehicle is in excellent condition with no significant issues like tears, stains, or damage observed in any of the described components.

VIN Inspection Report

VIN: 1HGBH41JXMN109186

Make & Model: 2017 Honda Civic Type R

Inspection Date: July 23, 2025

Inspector: AI-Powered System (AutoScope)

📍 Vehicle Overview

- Year: 2017
- Make: Honda
- Model: Civic Type R
- Trim: Touring
- Body Style: 4-door Hatchback
- Drive Type: Front-Wheel Drive (FWD)
- Engine: 2.0L VTEC Turbocharged I4
- Transmission: 6-Speed Manual
- Color: Championship White
- Fuel Type: Premium Unleaded Gasoline

⚠️ Accident History (1 Record)

- Date of Incident: 08/22/2020
- Type: Front Bumper Collision (Low-Speed Impact)
- Location: Dallas, TX
- Severity: Moderate cosmetic damage, no structural issues
- Airbags Deployed: No

- Repair Summary: Replaced front bumper and grille, resprayed to match factory color, repairs performed at certified Honda repair center
-

Odometer Verification

- Current Reading: 42,190 miles
 - Verified: Yes
 - Mileage Consistency: No irregularities found across inspections and service history
 - Last Recorded Reading: 39,900 miles on 01/03/2025
-

Service Records (12 Entries)

- Most Recent Service:
 - Date: 05/30/2025
 - Mileage: 41,850 mi
 - Work Performed:
 - Full synthetic oil change
 - 4-wheel alignment
 - Brake fluid flush
- Additional Notable Services:
 - 15,000 mi – Transmission fluid replaced
 - 20,000 mi – Performance air filter installed
 - 30,000 mi – New tires (Michelin Pilot Sport 4S)
 - 36,000 mi – Spark plugs replaced

to match factory color.

Title Check

- Status: Clean
 - Title State: Texas
 - Branded Title: No
 - Salvage/Rebuilt: No
 - Lien: Cleared
-

Usage Type

- Registered Use: Personal
 - Owners: 1
 - Rental/Fleet Use: None
 - Auction History: None found
-

Performance Modifications (Disclosed)

- Upgraded cat-back exhaust system (AWE Track Edition)
 - Carbon fiber rear wing (OEM-style)
 - Short throw shifter
 - Ceramic window tint
-

Factory Features & Options

Predicts how much value a car will lose over time based on mileage, condition, and market data. Helps users make smarter decisions before buying or selling.

7. Specialized Reports (JDM / Exotics / Auctions)

High-end visual reports tailored for rare or collector cars where appearance heavily impacts price. Premium upsell opportunity.

Why This Is a Full Business

- Multiple ways to make money — reports, listings, subscriptions, data, add-on tools
 - Tools connect and support each other — creating a full platform, not one-off features
 - Huge upside with more users — better AI, better data, more trust, more adoption
 - Future partner potential — works with dealerships, auction houses, car rental fleets, marketplaces, and repair chains
-

AutoScope isn't just solving one problem — it's building the infrastructure for smarter car ownership and resale.

Expansion Areas Already in Motion:

1. AutoList – AI Car Listings Generator

Automatically creates ready-to-post listings for Facebook Marketplace, Craigslist, CarGurus, etc. Pulls directly from AutoScope reports so sellers can go from inspection to live listing in seconds.

2. Dealer/Fleet Portal (AutoScope Pro)

Lets dealerships and fleet owners process cars in bulk. Branded reports, VIN uploads, photo imports — all built for volume and efficiency. Perfect for a monthly subscription model.

3. Data Dashboard – AutoIntel

Tracks trends from all inspections to deliver insights: what parts fail most, how condition impacts resale, etc. This data can be sold to marketplaces, repair shops, and insurance companies.

4. Mobile App

On-the-go inspections, VIN scanning, resale timing reminders. It turns AutoScope into a daily tool for car owners, not just sellers.

5. True Cost of Ownership Tool (App Idea)

Helps buyers understand the real cost of owning a car — fuel, insurance, maintenance, depreciation — based on actual data. A perfect add-on tool for dealerships, lenders, or car buyers.

6. Depreciation Forecast Tool (App Idea)

Predicts how much value a car will lose over time based on mileage, condition, and market data. Helps users make smarter decisions before buying or selling.

7. Specialized Reports (JDM / Exotics / Auctions)

High-end visual reports tailored for rare or collector cars where appearance heavily impacts price. Premium upsell opportunity.

Why This Is a Full Business

- Multiple ways to make money — reports, listings, subscriptions, data, add-on tools
- Tools connect and support each other — creating a full platform, not one-off features
- Huge upside with more users — better AI, better data, more trust, more adoption
- Future partner potential — works with dealerships, auction houses, car rental fleets, marketplaces, and repair chains

AutoScope isn't just solving one problem — it's building the infrastructure for smarter car ownership and resale.

Every new tool adds value. Every user fuels growth.