

ใบเสนอราคา

ผู้ขาย : บริษัท ชันน็อกซ์ จำกัด ☎ 0809643262
ที่อยู่ : เลขที่ 83/57 หมู่ที่ 10 ตำบลบางกร่าง
อำเภอเมืองนนทบุรี จังหวัดนนทบุรี 11000 ✉ info@sunnnox.co.th
เลขที่ภาษี : 0105564118633 (สำนักงานใหญ่) 🌐 -

เลขที่เอกสาร : QSPM-2026005
วันที่ออก : 14/01/2026
วันที่ตอบรับ : -
ใช้ได้ถึง : 21/01/2026
อ้างอิง : -

ลูกค้า : การไฟฟ้าฝ่ายผลิตแห่งประเทศไทย ☎ -
ที่อยู่ : เลขที่ 53 หมู่ 2 ถนน จรัญสนิทวงศ์ ✉ -
ตำบลบางกรวย อำเภอบางกรวย จังหวัด 🌐 -
นนทบุรี 11130
เลขที่ภาษี : 0994000244843 (สำนักงานใหญ่)

ติดต่อกลับที่ :

👤 nisa khem-thong
☎ 0942516132
✉ nisa.k@sunnnox.co.th

คำอธิบาย	จำนวน	ราคา	ส่วนลด	VAT	มูลค่าก่อนภาษี
1. Preventive Maintenance (1 ครั้ง) Corrective Maintenance (12 เดือน) Cleaning PV Module (3 Times / Year) *not included spare part โครงการ : Solar Rooftop E-GAT (ไทรน้อย) 4 buildings อ.ไทรน้อย จ.นนทบุรี Install Capacity : 540 KWp. PV Module : 990 Module (Follow Scope Of Work)	1.00	175,000.00	0.00	7%	175,000.00
ระยะเวลาดำเนินการ ตั้งแต่วันที่ 1 มีนาคม 2569 ถึงวันที่ 31 ธันวาคม 2569					


สรุป
มูลค่าที่คำนวณภาษี 7% 175,000.00 บาท
ภาษีมูลค่าเพิ่ม 7% 12,250.00 บาท
จำนวนเงินทั้งสิ้น หนึ่งแสนแปดหมื่นเจ็ดพันสองร้อยห้าสิบบาทถ้วน

จำนวนเงินทั้งสิ้น 187,250.00 บาท

จำนวนเงินที่ถูกหัก ณ ที่จ่าย 5,250.00 บาท
จำนวนเงินที่ชำระ 182,000.00 บาท

ชำระเงิน  ร.ไทยพาณิชย์
ออมทรัพย์ 0334330020
บริษัท ชันน็อกซ์ จำกัด

หมายเหตุ กำหนดการชำระเงิน/Term of payment
ชำระเงิน 100% หลังส่งมอบงาน
(ทาง ชันน็อกซ์ ขอยืนยันราคาตามที่เสนอ)

📄 รับรอง	สแกนเพื่อเปิดด้วยเว็บไซด์	Created by	Approved by	Stamp (Seller)	Received by (Customer)	Stamp (Customer)
		 nisa khem-thong 14/01/2026	 Paradorn Y 14/01/2026		 การไฟฟ้าฝ่ายผลิตแห่งประเทศไทย	



Sunnox Company Limited (Head Office)

83/57 M.10 Bang Krang Subdistrict Mueang Nonthaburi District Nonthaburi Province

RENEWABLE ENERGY Tel: 08-0964-3262 E-Mail: info@sunnox.co.th Tax ID: 0105564118633

Scope of Work			
Project	Preventive maintenance Solar Rooftop E-GAT (ไทรน้อย) 4 buildings (540 kWp)	Issue Date:	12/1/2026
Item	Description	Quantity	Frequency
1. Corrective Maintenance			
1.1	Corrective Maintenance		1 year
	- Onsite Service within 48 Hrs		
	- Summary Report		
2. Cleaning PV Modules			
2.1	Cleaning PV Module	990	3 times/year
	- Cleaning PV module with electical matchine		
	- Visual Inspection		
	- Report		
3. Preventive maintenance for following equipment			
3.1	ACP/MDB	4	3 times/year
	- Visual Inspection Check		
	- Cleaning Outside Panel Board		
	- Terminal Check & Tighten		
	- Voltage Check		
	- Current Check		
	- Pilot Lamp Check		
	- IR. Thermoscan		
	- Visual Terminal Check		
3.2	Inverter	6	3 times/year
	- Visual Inspection Check		
	- Cleaning outside and Inverter room		
	- DC Current Check		
	- LED Status		
	- IR. Thermoscan		
3.3	DC Fuse Boxes (If any)		3 times/year
	- Visual Inspection Check		
	- Cleaning		
	- Terminal Check & Tighten		
	- IR. Thermoscan		
	- Fuse Check		
3.4	Panel Board		3 times/year
	- Visual Inspection Check		
	- Cleaning		
	- Terminal Check & Tighten		
	- IR. Thermoscan		
3.5	Combiner Box		3 times/year
	- Visual Inspection Check		
	- Cleaning		

	- Terminal Check & Tighten		
	- IR. Thermoscan		
3.6	RTU Panel	4	3 times/year
	- Visual Inspection Check		
	- Cleaning inside and outside		
	- Terminal Check & Tighten		
	- IR. Thermoscan		
	- UPS Backup test		
	- Electrical Check (Voltage AC/DC)		
	- Recording value Check		
3.7	Battery energy storage system	1	3 times/year
	- Visual Inspection Check		
	- Check voltage level/Temperature Battery Module		
	- Cleaning cooling coils and drainage system.		
	- Check Fire extinguishing and safety systems		
	- Check PCS		
3.8	PV Module & Structures	990	3 times/year
	- Visual Inspection Check		
3.9	Drone Thermal Inspection	990	3 times/year
	- PV Modules		
	- Report		
3.10	Ground System		3 times/year
	- Ground resistance		
	- Ground continue		