All System Diagnostic Report

The Report is created by Ediag

Vehicle Information

SN:9TBC29728913
Make:OPEL
Model:Astra-G
Year:1999
VIN:W0L0TGF69X5059457
Mileage:0 Miles
Test Time:10/05/2026 16:50:52

Inspection Result

Engine 5 problems exist

1.P0340-0 Camshaft Sensor Incorrect Signal
Not Present

2.P0105-1 Manifold Absolute Pressure (MAP) Sensor Voltage High
Not Present

3.P0200-0 Fuel Injector Circuit(s)
Not Present

4.P0335-8 Incorrect RPM Signal
Not Present

5.P0607-0 Knock Control Module; Replace Electronic Control Unit (ECU)
Not Present

Airbag SAB6 2 problems exist

1.16 Driver Pre-tensioner belt Signal too large
Invalid

2.25 Passenger Airbag Squib Circuit Signal High
Invalid

IC-Instrument Cluster 1 problems exist

1.164 Engine Coolant Temperature Incorrect Signal
Not Present

Radio CDR 500 1 problems exist

1.41 No FM Radio Stations Found
Present

The following systems are OK:

1.ABS-5.3/5.4(+TC) -ABS-Antilock Brake Module-5.3/5.4(+TC)
2.CDL-Central Door Lock
3.IMMO-Immobiliser
4.TID-Trip Info Display