AI Damage Inspection Report

Generated by CrackEye System

Detection Output

Location Details

Area: 18.931751, 73.162266

Latitude: None

Longitude: None

Damage Analysis

Type: crack

Category: infrastructure

Severity: low

Confidence: 45.0%

Geometry Metrics

Mask Area: 136.6

BBox Area: 13536

Risk Assessment

Risk Score: 2.06

Priority: low

Traffic Impact: high

Recommended Action

Action: crack sealing

Method: injection sealing

Material: epoxy resin

Estimated Cost: ■8.2

Time Required: 2 hrs