AI Damage Inspection Report

Generated by CrackEye System

Detection Output

Location Details

Area: 18.931914, 73.162251

Latitude: None

Longitude: None

Damage Analysis

Type: crack

Category: infrastructure

Severity: low

Confidence: 53.0%

Geometry Metrics

Mask Area: 575.3000000000001

BBox Area: 143060

Risk Assessment

Risk Score: 2.31

Priority: low

Traffic Impact: high

Recommended Action

Action: crack sealing

Method: injection sealing

Material: epoxy resin

Estimated Cost: ■34.52

Time Required: 2 hrs