

SOVEREIGN INDUSTRIAL INSPECTION REPORT

Date: 2026-09-16

Inspector: Quality Assurance Team Alpha

Facility: Turbine Unit 4

EQUIPMENT IDENTIFICATION:

Equipment ID: V-204

Component: Main High-Pressure Flange Seal

Serial Number: SN-99482-FLG

INSPECTION FINDINGS:

Finding: Critical seal wear detected on main flange.

Measurement: 0.15 mm clearance

Safety Threshold: 0.10 mm maximum allowable tolerance

Status: FAILED TOLERANCE SPECIFICATION

MAINTENANCE ACTION REQUIRED:

Recommendation: Immediate flange seal replacement required prior to re-pressurization.