







## MAGNETIC PARTICLE TESTING REPORT

Client	: ACCESS IN-SITU MACHINING	Site Location	Himalayan Power partner Ltd : Lamjung District Ramchowk Besi, Besisahar 11		
Report No	: MTPL/NDT/MPI/07-001	Date of Inspection	: 07-07-2023		
EQUIPMENT	: Electro Magentic Yoke	CALIBRATION BLOCK	: PIE Gauge		
MACHINE MODEL	: -	Visible Line	: 6 lines		
MACHINE SI NO	: 201704397	TEMPERATURE	: Ambient		
CALIBTATION	: 29-Jun-24	SURFACE CONDITION	: Smooth		
MATERIAL SPECIFICATION	REFERENCE STANDARD	TEST PROCEDURE	ACCEPTANCE STANDARD		
MS	ASME Sec-7	MTPL-ASME-NDT-MT-001	Appendix 6		
<b>REMARKS:</b> NO Significant indications Found					
SI NO	JOB NAME	THICKNESS	ID	OD	RESULT
1	TURBINE FLY WHEEL	250mm	618.5mm	2350mm	Accepted
<b>SKETCH:</b> <div style="display: flex; justify-content: space-around;">   </div>					
INSPECTED BY		APPROVED BY		CLIENT REPRESENTATIVES	
NAME	: M.U. MOHAMMED RAFIQ ASLAM	NAME	: N VELMURUGAN	NAME	:
SIGNATURE	: 	SIGNATURE	: 	SIGNATURE	:
DESIGNATION	: NDT Technician	DESIGNATION	: NDT Coordinator	DESIGNATION	:
DATE	: 07-Jun-23	DATE	: 07-Jul-23	DATE	:
Address: "H.M. SQUARE", No.23, 1st Floor, Kamaraj Avenue 1st Street, Kasturba Nagar, Adyar, Chennai - 20 Email: enquiry@maitravaruna.com, Ph: 8925032229 / 8925042229 / 7418642229					