Crew Behavior Monitoring Report

Generated: 2026-03-09 09:11:20 | File: WhatsApp Video 2026-01-19 at 2.01.25 PM (2).mp4 | Duration: 714s | Frames Analyzed: 200

#1 Crew Alertness

Status: MODERATE

Gemini analysis of 100 frames: HIGH=11, MODERATE=70, LOW=19. PERCLOS=26.0% (52/200 frames with impaired eyes). Head drooping in 59 frames. Yawning detected in 5 frames. Alertness composite score: 0.22.

Confidence: HIGH



#2 Crew Distraction

Status: OBSERVED

Gemini: 32/100 frames flagged (32%). One crew member appears focused on paperwork. | One crew member appears to be writing/reading, diverting attention. | One crew member has their arm raised away from the controls.

Confidence: HIGH



Crew Behavior Monitoring Report

Generated: 2026-03-09 09:11:20 | File: WhatsApp Video 2026-01-19 at 2.01.25 PM (2).mp4 | Duration: 714s | Frames Analyzed: 200

#3 Crew Doing Writing Work

Status: OBSERVED

Gemini: 82/100 frames flagged (82%). Paperwork visible on the console. | Crew member is looking at/writing on the paperwork. | Documents visible on the console may be being read/written on.

Confidence: HIGH



#4 Crew Taking Nap / Micro-sleep

Status: OBSERVED

Gemini: 10/100 frames flagged (10%). One crew member's posture and closed eyes suggest napping. | Closed eyes and tilted head suggest possible napping. | One crew member appears to be napping.

Confidence: HIGH



Crew Behavior Monitoring Report

Generated: 2026-03-09 09:11:20 | File: WhatsApp Video 2026-01-19 at 2.01.25 PM (2).mp4 | Duration: 714s | Frames Analyzed: 200

#5 Crew Using Mobile

Status: NOT_OBSERVED

Gemini: 5/100 frames flagged (5%). Crew member appears to have a phone to their ear. | One crew member is potentially using a mobile phone. | Crew member in the front has a hand raised near ear with small object

Confidence: MEDIUM



#6 Crew Packing Belongings

Status: NOT_OBSERVED

Gemini: 0/100 frames flagged (0%). No specific evidence.

Confidence: HIGH

#7 Crew Leaving Place

Status: NOT_OBSERVED

Gemini: 2/100 frames flagged (2%). Crew member appears to be in the process of leaving/entering. | One crew member is in the act of leaving.

Confidence: MEDIUM



Crew Behavior Monitoring Report

Generated: 2026-03-09 09:11:20 | File: WhatsApp Video 2026-01-19 at 2.01.25 PM (2).mp4 | Duration: 714s | Frames Analyzed: 200

#8 Crew Operating Horn Lever/Switch

Status: NOT_OBSERVED

Gemini: 0/100 frames flagged (0%). No specific evidence.

Confidence: HIGH

#9 LP Applying A9/SA9 After Halt

Status: OBSERVED

A9/SA9 brake application detected by custom YOLO in 100/200 frames (18 consecutive). Strong evidence of brake application. Gemini corroboration: 11/100 frames (11%). Hand on brake handle. | Crew member has hand on brake handle.

Confidence: HIGH



Overall Safety Assessment

Gemini analyzed 100 frames, flagged 4 concern(s): napping/micro-sleep detected, crew distraction, writing work during duty, A9/SA9 brake application detected.

Recommendations

- Monitor crew alertness levels. Consider breaks or interventions.
- CRITICAL: Napping detected. Immediate intervention required.
- Address crew distraction. Remind crew to focus on track and controls.
- A9/SA9 brake application after halt detected. Confirm proper braking procedure followed.